
BLA-PIMOT-MK1 WIP #1 Front Projection



1 -> Idle Indicator
2 -> Active Indicator
3 -> Connect Indicator
4 -> Arm Indicator
5 -> Run Indicator