

PROJ: 8777 FSF W/O: 3701800
 P/N: 113W9335-1 FRAME QTY: 1
 S/N: K0883 CLASS: P FAI
 INSP: KE2113 DATE: 12APR2010
 Remark: MODEL:DUKIN CMM (C/N:AF00007717)

SEQ	TASK	Actual	Nominal	U-Tol	L-Tol	DEV	EVAL
1	MCS						
2	1CMT 8777 FSF 113W9335-1 SEGMENT FRAME CMM PROG						
3	PROG. NAME = F9335A.HLP						
4	PROG. REV. = A						
5	DWG. NO. = 113W9335-1						
6	DWG. REV. = 0						
7	PART. NAME = FRAME						
8	CS Recall < PCS Recall						
9	NOO						
10	PLS ALIGNMENT PER SETUP SKETCH						
11	MODEL = C42KHJ.930323.W.113W9335S01-D-1.....-1.FRAME.SEGMENT						
12	NC SET:= PROBE1						
13	N010						
14	====>>> START OF MEASURING <<<====						
15	\$INSP OF HOLE						
16	N011						
17	HOL_12(1)						
	X	-3.2157	-3.2128	0.0100	-0.0100	0.0029	++
	Y	-2.9255	-2.9211	0.0100	-0.0100	0.0044	++
	Z	0.0799					
	D	0.3776	0.3750	0.0100	-0.0100	0.0026	++
	POS (d)0.0105	0.0200	(M)0.0326				++
	Smm 4P	0.0001	0.0001	-0.0001			
18	N012						
19	\$INSP OF KEY PT						
20	N013						
21	N014						
22	N015						
23	N016						
24	pnt_17						
	X	-2.5002	-2.5000	0.0100	-0.0100	0.0002	+
	Y	-3.4399	-3.4364	0.0100	-0.0100	0.0035	++
	Z	-0.0001	0.0000	0.0100	-0.0100	-0.0001	-
	PRS	0.0035	0.0000	0.0100	-0.0100	0.0035	++
25	N017						
26	N018						
27	pnt_19						
	X	0.7497	0.7500	0.0100	-0.0100	-0.0003	-
	Y	-3.7313	-3.7281	0.0100	-0.0100	0.0032	++
	Z	-0.0002	0.0000	0.0100	-0.0100	-0.0002	-
	PRS	0.0032	0.0000	0.0100	-0.0100	0.0032	++
28	N019						
29	\$INSP OF SURFACE						
30	N020						
31	pnt_21						
	X	-3.1925	-3.1925	0.0100	-0.0100	0.0000	><
	Y	-3.4794	-3.4745	0.0100	-0.0100	0.0049	++
	Z	0.7397	0.7400	0.0100	-0.0100	-0.0003	-
	PRS	0.0049	0.0000	0.0100	-0.0100	0.0049	++
32	N021						
33	pnt_22						
	X	-2.0968	-2.0967	0.0100	-0.0100	0.0001	><
	Y	-3.4785	-3.4725	0.0100	-0.0100	0.0060	+++
	Z	0.7396	0.7400	0.0100	-0.0100	-0.0004	-
	PRS	0.0060	0.0000	0.0100	-0.0100	0.0060	+++
34	N022						
35	pnt_23						
	X	-0.7672	-0.7657	0.0100	-0.0100	0.0015	+
	Y	-3.4975	-3.4905	0.0100	-0.0100	0.0070	+++
	Z	0.7396	0.7400	0.0100	-0.0100	-0.0004	-
	PRS	0.0071	0.0000	0.0100	-0.0100	0.0071	+++
36	N023						
37	pnt_24						
	X	-0.3727	-0.3678	0.0100	-0.0100	0.0049	++

	Y	-3.6737	-3.6670	0.0100	-0.0100	0.0067	+++
	Z	0.7398	0.7400	0.0100	-0.0100	-0.0002	-
	PRS	0.0063	0.0000	0.0100	-0.0100	0.0063	+++
38	N024						
39	pnt_25						
	X	-0.1519	-0.1514	0.0100	-0.0100	0.0005	+
	Y	-3.7557	-3.7526	0.0100	-0.0100	0.0031	++
	Z	0.7398	0.7400	0.0100	-0.0100	-0.0002	-
	PRS	0.0031	0.0000	0.0100	-0.0100	0.0031	++
40	N025						
41	pnt_26						
	X	0.7323	0.7327	0.0100	-0.0100	-0.0004	-
	Y	-3.7606	-3.7561	0.0100	-0.0100	0.0045	++
	Z	0.7397	0.7400	0.0100	-0.0100	-0.0003	-
	PRS	0.0045	0.0000	0.0100	-0.0100	0.0045	++
42	N026						
43	pnt_27						
	X	2.7327	2.7327	0.0100	-0.0100	0.0000	><
	Y	-3.7736	-3.7687	0.0100	-0.0100	0.0049	++
	Z	0.7399	0.7400	0.0100	-0.0100	-0.0001	-
	PRS	0.0049	0.0000	0.0100	-0.0100	0.0049	++
44	N027						
45	pnt_28						
	X	4.7325	4.7326	0.0100	-0.0100	-0.0001	><
	Y	-3.7918	-3.7875	0.0100	-0.0100	0.0043	++
	Z	0.7400	0.7400	0.0100	-0.0100	0.0000	><
	PRS	0.0043	0.0000	0.0100	-0.0100	0.0043	++
46	N028						
47	pnt_29						
	X	5.7319	5.7325	0.0100	-0.0100	-0.0006	-
	Y	-3.8047	-3.7994	0.0100	-0.0100	0.0053	+++
	Z	0.7399	0.7400	0.0100	-0.0100	-0.0001	><
	PRS	0.0053	0.0000	0.0100	-0.0100	0.0053	+++
48	N029						
49	pnt_30						
	X	6.7317	6.7324	0.0100	-0.0100	-0.0007	-
	Y	-3.8174	-3.8128	0.0100	-0.0100	0.0046	++
	Z	0.7401	0.7400	0.0100	-0.0100	0.0001	+
	PRS	0.0046	0.0000	0.0100	-0.0100	0.0046	++
50	N030						
51	pnt_31						
	X	7.7317	7.7323	0.0100	-0.0100	-0.0006	-
	Y	-3.8298	-3.8278	0.0100	-0.0100	0.0020	+
	Z	0.7401	0.7400	0.0100	-0.0100	0.0001	+
	PRS	0.0020	0.0000	0.0100	-0.0100	0.0020	+
52	N031						
53	pnt_32						
	X	8.7315	8.7322	0.0100	-0.0100	-0.0007	-
	Y	-3.8463	-3.8444	0.0100	-0.0100	0.0019	+
	Z	0.7403	0.7400	0.0100	-0.0100	0.0003	+
	PRS	0.0019	0.0000	0.0100	-0.0100	0.0019	+
54	N032						
55	pnt_33						
	X	9.7313	9.7320	0.0100	-0.0100	-0.0007	-
	Y	-3.8646	-3.8626	0.0100	-0.0100	0.0020	+
	Z	0.7399	0.7400	0.0100	-0.0100	-0.0001	-
	PRS	0.0020	0.0000	0.0100	-0.0100	0.0020	+
56	N033						
57	pnt_34						
	X	10.7310	10.7318	0.0100	-0.0100	-0.0008	-
	Y	-3.8841	-3.8823	0.0100	-0.0100	0.0018	+
	Z	0.7398	0.7400	0.0100	-0.0100	-0.0002	-
	PRS	0.0019	0.0000	0.0100	-0.0100	0.0019	+
58	N034						
59	pnt_35						
	X	11.7307	11.7316	0.0100	-0.0100	-0.0009	-
	Y	-3.9050	-3.9037	0.0100	-0.0100	0.0013	+
	Z	0.7399	0.7400	0.0100	-0.0100	-0.0001	-
	PRS	0.0013	0.0000	0.0100	-0.0100	0.0013	+
60	N035						
61	pnt_36						
	X	12.5589	12.5599	0.0100	-0.0100	-0.0010	-
	Y	-3.9243	-3.9226	0.0100	-0.0100	0.0017	+
	Z	0.7398	0.7400	0.0100	-0.0100	-0.0002	-
	PRS	0.0017	0.0000	0.0100	-0.0100	0.0017	+