

Smarter technology for all

# Project Assurance Resolution Team Performance Review

Lenovo

Ahmed Mohsen | May 11, 2026

# Project ART – Objectives

*Ensure customer issues are fully resolved and validated before Work Order (WO) closure, delivering resolution assurance and strengthening confidence in Service Delivery.*

## Key Responsibilities

### 1. Proactive follow-up prior to WO closure

- Engage customers via SMS, email, and phone to confirm whether their issue has been resolved.
- Ensure customer sentiment and resolution status are captured before the survey is triggered.

### 2. Capture Customer Response Outcomes

Customers indicate one of three outcomes:

1. Problem Resolved
2. Problem Not Resolved
3. Opt Out

### 3. Drive Case Continuity & Customer Satisfaction


- When a customer reports ***Problem Not Resolved***, Project ART conducts troubleshooting and, if necessary, opens a new Work Order (WO) under the same case to ensure timely re-engagement and completion.

### 4. Monitor Trends to Improve Service Delivery

- Track and analyze Problem Not Resolved trends.
- Identify recurring issues or process gaps.
- Share insights and recommendations with Lenovo to support service improvement and customer experience enhancement.


# Emails Yields the Highest Customer Response Rate

## Overall Monthly Project ART Case Volume & Reach Attempt Performance




| Month         | Emails |     | SMS  |     | Calls |     | ART Cases | Reach Rate |
|---------------|--------|-----|------|-----|-------|-----|-----------|------------|
| January 2026  | 1204   | 41% | 951  | 32% | 800   | 27% | 5378      | 55%        |
| February 2026 | 1696   | 45% | 1118 | 30% | 918   | 25% | 7003      | 53%        |
| March 2026    | 1499   | 47% | 955  | 30% | 731   | 23% | 6534      | 49%        |
| April 2026    | 1330   | 44% | 884  | 29% | 785   | 26% | 6252      | 48%        |

# 35% of April ART Cases are Resolved







| Month    | No Reply |     | Issue Resolved |     | DND   |     | Issue Not Fixed |    | Not yet Tested |    | Escalated |      | Total Cases |
|----------|----------|-----|----------------|-----|-------|-----|-----------------|----|----------------|----|-----------|------|-------------|
|          | Cases    | %   | Cases          | %   | Cases | %   | Cases           | %  | Cases          | %  | Cases     | %    |             |
| January  | 2430     | 45% | 2180           | 41% | 336   | 6%  | 266             | 5% | 152            | 3% | 14        | 0.3% | 5378        |
| February | 3252     | 46% | 2693           | 38% | 450   | 6%  | 412             | 6% | 146            | 2% | 50        | 0.7% | 7003        |
| March    | 3177     | 49% | 2477           | 38% | 496   | 8%  | 238             | 4% | 121            | 2% | 25        | 0.4% | 6534        |
| April    | 2917     | 47% | 2170           | 35% | 628   | 10% | 348             | 6% | 153            | 2% | 36        | 0.6% | 6252        |
| Total    | 11776    | 47% | 9520           | 38% | 1910  | 8%  | 1264            | 5% | 572            | 2% | 125       | 0.5% | 25167       |

# Escalated Cases Breakdown





| Escalations/Month | January |      | February |      | March |      | April |      | Grand Total |      |
|-------------------|---------|------|----------|------|-------|------|-------|------|-------------|------|
| DRO Team          | 310     | 75%  | 337      | 82%  | 351   | 77%  | 347   | 78%  | 1345        | 78%  |
| LenCare Team      | 102     | 25%  | 76       | 18%  | 106   | 23%  | 96    | 22%  | 380         | 22%  |
| Grand Total       | 412     | 100% | 413      | 100% | 457   | 100% | 443   | 100% | 1725        | 100% |

# Project ART T3B vs. Non-Project ART T3B by SDT





# How are Depot Customers Responding to Project ART Follow-ups?

## Reach Attempt Performance & Customer Response Outcomes



# How are ONS Customers Responding to Project ART Follow-ups?



## Reach Attempt Performance & Customer Response Outcomes






# How are CRU Customers Responding to Project ART Follow-ups?

## Reach Attempt Performance & Customer Response Outcomes





# Depot Machine Types 21BV & 21HH are Driving Issue Not Fixed

Machine Types 21BV and 21HH represent 7% of all Issue Not Fixed reports for Depot repairs of April




| Root Cause Insights | Value                                                   | Count | %      | Root Cause Insights | Value                             | Count | %      |
|---------------------|---------------------------------------------------------|-------|--------|---------------------|-----------------------------------|-------|--------|
| Parts Sent          | System Board                                            | 6     | 75.00% | Second Parts Sent   | NA (single WO)                    | 7     | 87.50% |
|                     | Fan / No parts replaced                                 | 2     | 25.00% |                     | Keyboard, SSD                     | 1     | 12.50% |
|                     |                                                         |       |        | RR Reason           | NA (single WO)                    | 6     | 75.00% |
| New Issue           | Same issue                                              | 3     | 37.50% |                     | Workmanship / Previous WO NTF/SBU | 2     | 25.00% |
|                     | NA (single WO)                                          | 2     | 25.00% |                     |                                   |       |        |
|                     | Others (Fan not detected, SSD error, touchscreen issue) | 3     | 37.50% |                     |                                   |       |        |

# Why Were Second Work Orders Required for Depot?





# ONS Machine Types 21AJ & 21HE are Driving Issue Not Fixed

Machine Types 21AJ and 21HE represent 11% of all Issue Not Fixed reports for ONS repairs this month




| Root Cause Insights | Value                            | Count | %      | Root Cause Insights | Value                                            | Count | %      |
|---------------------|----------------------------------|-------|--------|---------------------|--------------------------------------------------|-------|--------|
| Parts Sent          | System Board                     | 11    | 84.60% | New Issue           | Same issue                                       | 3     | 23.10% |
|                     | Keyboard / Touchpad              | 2     | 15.40% |                     | Hardware (SSD, Battery, Screen, Touchpad, Mouse) | 5     | 38.50% |
| RR Reason           | NA (No Repeat Reason)            | 6     | 46.20% |                     | BitLocker                                        | 2     | 15.40% |
|                     | Part DOA                         | 2     | 15.40% |                     | Others (SSD error)                               | 3     | 23.10% |
|                     | Customer Induced / Part Delivery | 3     | 23.10% | Second Parts Sent   | NA                                               | 6     | 46.20% |
|                     | Workmanship / Unrelated Issue    | 2     | 15.40% |                     | System Board                                     | 2     | 15.40% |
|                     |                                  |       |        |                     | Others (SSD, Adapter, Mouse pad, etc.)           | 5     | 38.50% |

# Why Were Second Work Orders Required for ONS?




# 11 Different CRU Machine Types Driving Issue Not Fixed




| Root Cause Insights | Value                                                | Count | %      | Root Cause Insights | Value                                             | Count | %      |
|---------------------|------------------------------------------------------|-------|--------|---------------------|---------------------------------------------------|-------|--------|
| Parts Sent          | AC Adapter                                           | 5     | 38.50% | RR Reason           | NA (Single WO)                                    | 11    | 84.60% |
|                     | Keyboard                                             | 3     | 23.10% |                     | Incorrect AC / Part Delivery                      | 2     | 15.40% |
|                     | Others (Docking station, Wireless key/headset, etc.) | 5     | 38.50% | New Issue           | Same issue                                        | 4     | 30.80% |
| Second Parts Sent   | NA (single WO)                                       | 11    | 84.60% |                     | Other (Refurbished parts, CX asking for SSR, ...) | 6     | 46.20% |
|                     | AC Adapter + Power / Keyboard                        | 2     | 15.40% |                     | NA / Part Delivery                                | 3     | 23.10% |

# Why Were Second Work Orders Required for CRU?



# Open Care Call Cases





# Backup Slides

# PART Post Repair Outreach Process

## Customer Response Handling

1. If the customer replies "1", this indicates that the issue has been fully resolved.
  - a. For SMS responses, the case will automatically close.
  - b. For email responses, the PART must manually close the case in MSD.
2. If the customer replies "2" or "Need Assistance", the PART must immediately contact the customer and update the case status in MSD to Care Call (**do not update the case reason**).
  - a. The PART must attempt to contact the customer for an additional five (5) days. If there is still no response after this period, ensure that the **case level survey preference** is set to "No", send the Case Closure email to the customer, document the outreach in MSD, and update the case status to Closed.
  - b. If the customer is responsive, assist the customer following business-as-usual procedures. No changes should be made to the case reason or status unless otherwise specified in applicable quality advisories.
3. If the customer indicates that they need more time to observe the machine before confirming the service outcome, the PART must ask for the customer's preferred date and time for follow-up.
  - a. If no definite time is provided, the PART must attempt to contact the customer for an additional five (5) days. If there is still no response after this period, the case status may be updated to Solution Provided and allowed to close naturally.
4. If the customer replies "3" or "Stop", the PART must update the case reason to Escalation/Complaint, change the channel preference (SMS, Email, Callback) to "No", and document the outreach outcome in the MSD case notes.

## Outreach Cadence

Review the case first to determine the customer's preferred contact method. If there is no preference specified, proceed using the process below:

### PART Agent Day 1 – Initial

- Initiate contact with the customer via the SMS channel.
- Use the appropriate SMS template based on the work order type.

### PART Agent Day 2 – Follow Up

- If no response is received on Day 1, contact the customer via email.
- Use the applicable Email template based on the work order type.

### PART Agent Day 3 – Second Follow Up

- If there is still no response after the email outreach, attempt to contact the customer via phone using the Customer Recovery Script available on the Project ART Hub.
- If the customer is unreachable, send an email using the appropriate "Routed to Voicemail" template based on the work order type.

### PART Agent Day 4 – Final Action

- If no response is received after all outreach attempts, send the "Case Closure Email" to the customer.
- This communication notifies the customer that multiple contact attempts were made without response, that the case will be closed, and that a survey will be sent.

**Smarter  
technology  
for all**

**Lenovo**

**thanks.**