


(a)



(b)

$$\mathbf{C}_{dd} = \begin{bmatrix} c_{d1d1} & c_{d1d2} \\ c_{d2d1} & c_{d2d2} \end{bmatrix}$$

$$\mathbf{C}_{dg} = \begin{bmatrix} c_{d1g1} & c_{d1g2} & c_{d1g3} \\ c_{d2g1} & c_{d2g2} & c_{d2g3} \end{bmatrix}$$

$$\mathbf{C}_{sd} = [c_{s1d1} \quad c_{s1d2}]$$

$$\mathbf{C}_{sg} = [c_{s1g1} \quad c_{s1g2} \quad c_{s1g3}]$$

- plunger gate to its own dot — the honeycomb period
- cross-coupling — the slope of the two line families
- interdot — the anticrossing
- the sensor's couplings — readout
- gate 3 to the dots — the smallest entries of Table I