Comparative table for clone ttester

Clone model	CPU, form factor, clock	Display, controller, resolution	5V reg, ref.2.5V, power control	Test option (preinstalled firmware)	Protection will measure ports	Firmware, opportunity update	Power supply	Possible price
LCR-T4	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI 14pin, ST7565, 128x64	78L05, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Chinese firmware (2.07-2.68), possible update to firmware 1.13k or 1.42m	+9V	≥6-10\$
Fish-8840	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI 6pin, ST7565, 128x64	78L05, No, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Chinese firmware 2.1, possible update to firmware 1.13k or 1.42m	+9V	≥15-20\$
M328Kit+TFT(AY-AT)	ATMega328, DIP, 8Mhz	LCD TFT 1.8" SPI 8pin, ST7735, 160x128	7550, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors voltmeter, frequency generator, frequency meter, encoder	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Firmware 1.12k mod., possible update to firmware 1.13k or 1.42m	+9V, connector ext. 9-12V	≥10-15\$

GM328A	ATMega328, DIP, 8Mhz	LCD TFT 1.8" SPI 8pin, ST7735, 160x128	7550, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors voltmeter, frequency generator, frequency meter, encoder	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Firmware 1.12k mod., possible update to firmware 1.13k or 1.42m	+9V, connector ext. 9-12V	≥10-15\$
M328Kit Carranation Leater N-E-MOS 123=SDG C=7.64nF Vt=3.6V 1-H-2 Uf=583mV	ATMega328, DIP, 8Mhz	LCD 2.4" SPI 8pin, ST7565, 128x64	7550, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors voltmeter, frequency generator, frequency meter, encoder	No	Firmware 1.12κ mod.*, possible update to firmware 1.13κ or 1.42m	+9V	≥10-15\$
GM328A+ GM328 IR TESTER Bat. 8.1U OK! UCC=5.81U CORRECTION OF AUGUST AND AUGUST AUGU	ATMega328, TQFP or DIP, 8Mhz	LCD 2.6" SPI 9pin or 16pin, ST7565, 128x64	7550, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Firmware 1.11k mod.*, possible update to firmware 1.13k or 1.42m	+9V	≥10-15\$
MG328	ATMega328, TQFP, 8Mhz	LCD 2.4" SPI 8pin, ST7565, 128x64	7150, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Firmware 1.11k mod., possible update to firmware 1.13k or 1.42m	+3.7V, +5V(USB)	≥10-15\$

WEI M8-1	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI 8pin, ST7565, 128x64	7150, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Firmware 1.11k mod., possible update to firmware 1.13k or 1.42m	+3.7V, +5V(USB)	≥10-15\$
BSIDE ESR02(DTU-1701B)	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI 10pin, ST7565, 128x64	7150, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Firmware 1.11κ mod., possible update to firmware 1.13κ or 1.42m	+9V, connector ext. 9-12V	≥25-30\$
Fish-8840(BOX) Transistor tester PITERFACE FIFTH TO THE TEST OF	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI 12pin, ST7565, 128x64	78L05, No, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Chinese firmware 2.1, possible update to firmware 1.13k or 1.42m	+9V	≥10-15\$
Fish-8840TFT 30 Form	ATMega328, TQFP, 8Mhz	LCD TFT 1.8" SPI 14pin, ST7735S, 160x128	78L05, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	No	Chinese firmware 2.4*, possible update to firmware 1.13k or 1.42m	+9V	≥15-20\$

Multi-function Tester - TC1 R-T-cater Selftest End vo.10 123 123 2 R AA1233 A how didney blow soring	ATMega324, TQFP, possible ATMega644, 16Mhz	LCD TFT 1.8" SPI 6pin, ST7735S, 160x128	78L05, TL431, port PA5, STC15L104, possible STC15F104, STC15W104	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<35V), voltmeter, resistors, capacitors, chokes, inductors, IR receiver	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Chinese firmware 2.12, possible update to firmware 1.13k or 1.41m**	+3.7V, USB charging	≥15-20\$
LCR-T7(1) Interest Interest	ATMega324, (TQFP), possible ATMega644, 16Mhz	LCD TFT 1.8" SPI 14pin, unknown, 128x128	78L05, TL431, port PA5, STC15L104, possible STC15F104, STC15W104	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<35V), voltmeter, resistors, capacitors, chokes, inductors, IR receiver	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Chinese firmware 2.12*	+3.7V, USB charging	≥15-20\$
LCR-T7(2)	ATMega324, (TQFP), possible ATMega644, 16Mhz	LCD TFT 1.8" SPI 6pin, ST7735S, 160x128	78L05, TL431, port PA5, STC15L104, possible STC15F104, STC15W104	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<35V), voltmeter, resistors, capacitors, chokes, inductors, IR receiver	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Chinese firmware 2.12, possible update to firmware 1.13k or 1.41m**	+3.7V, USB charging	≥15-20\$
Multi-function Tester - III	ATMega324, (TQFP), possible ATMega644, 16Mhz	LCD TFT 1.8" SPI 14pin, unknown, 128x128	78L05, TL431, port PA5, STC15L104, possible STC15F104, STC15W104	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<20V), voltmeter, resistors, capacitors, chokes, inductors, IR receiver	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Chinese firmware 2.12*	+3.7V, USB charging	≥15-20\$

MK-328 MK-328 TRICREST TENTR 1-#-2 Ur=1, 740 C=11pF Date grapacite Selection misseles 1 3 3 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4 4	ATMega328, TQFP, 8Mhz	LCD 2.6" SPI, ST7565, 128x64	1117, TL431, divider port PC5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<5V), resistors, capacitors, chokes, inductors	Yes, SRV05-4 diode assembly, suppressor (TVS) 6V8A	Firmware 1.11k mod., possible update to firmware 1.13k or 1.42m	+9V	≥18-25\$
Hiland M644 Transistor tester LF quartz f=32.768kHz / T=30.52327µs f=32.76189kHz	ATMega644, TQFP, 8Mhz	LCD 2.4" SPI 8pin, ST7565, 128x64	1117, TL431, divider port PA5	Transistors, diodes, diode assemblies, LEDs, thyristors, triacs, zener diodes (<35V), resistors, capacitors, chokes, inductors, frequency generator, frequency meter, quartz and ceramik resonators, voltmeter, encoder	No	Firmware 1.12k mod.*, possible update to firmware 1.13k or 1.42m	+ 9V	≥18-25\$

^{*} Note: the Chinese version is locked to read!

^{**} Note: for a clone with a display connected to a 6-pin J3 connector.