Errata

Publication I

In Section IIIA, the bandwidths B_8 and B_9 should be set to $B_8 = 1.395\,\omega_{c,8}$ and $B_9 = 1.17\,\omega_{c,9}$, respectively.