GATE 2 · THE CHECKPOINT INTO TIER 2 · WITNESSED

Pavo 20 Pro Flight


Checkpoint into Tier 2: fly the Pavo 20 Pro.

TO PASS

1. Takeoff with a spotter
2. A figure-eight
3. An orbit
4. Through a gate
5. A clean landing on the pad - no contact

In person with a mentor, everything in one flight, one attempt per day.

THROUGH THE GATE YOU FLY THE PAVO 20 PRO · SHEET 3 →



6

FLIGHT · WITNESSED

Freestyle Flight

1. Smooth, flowing lines
2. Three tiny gaps
3. A powerloop
4. A trippy spin
5. A Matty flip
6. A wildcard · a path or move the mentor picks at random

In person with a mentor, everything in one flight, one attempt per day.

5

BUILD & TECH · BENCH

Field Diagnostics

1. A mentor breaks three things without telling you what
2. Radio: find and fix it
3. Betaflight: find and fix it
4. Mechanical or electrical: find and fix it
5. Explain each cause to the mentor
6. Photo of your work on the website · a mentor passes it

4

KNOWLEDGE & SAFETY · QUIZ

Radio Protocol

1. Pass the Radio Protocol quiz · 80 % or better · no sign-off needed

Covers: Analog against digital · Bands, channels and racing · Antennas and diversity · Control links: ELRS, Crossfire, binding, failsafe · Interference at an event · Digital video: goggles, recording and D-log

3

KNOWLEDGE & SAFETY · QUIZ

Electrical Components

1. Pass the Electrical Components quiz · 80 % or better · no sign-off needed

Covers: The six parts · Motors, props and thrust · Matching motor, ESC, prop and battery · Why a 3-inch and a 5-inch differ

2

BUILD & TECH · BENCH

Betaflight

1. Props OFF, battery OUT, USB only, then connect (the kiosk reads the board)
2. Flash the practice config (a lightly messed-up drone)
3. Receiver protocol; modes: ARM and angle; set the rates
4. Motors: order and direction (props off!)
5. OSD: battery usage and amp draw, positioned
6. Check my work - the kiosk compares with the stock config
7. Photo of your work on the website · a mentor passes it

On the club Meteor 75 Pro at the kiosk. Betaflight Intro (Tier 1 path) covered the accelerometer and binding.

1

BUILD & TECH · BENCH

Soldering

1. Iron at the right temperature, tip tinned
2. Tin the pad, tin the wire, join
3. ESC pads: shiny, no bridges
4. Motor wires: all three, trimmed
5. Spin each motor in Betaflight (props off)
6. Photo of your work on the website · a mentor passes it



FROM SHEET 1
Gate 1 passed: you fly the club Meteor