C:\Documents And Settings\User\Desktop\BurnInStatic\Documentation

- 0) Boot up the computer to the Desktop. There should be a folder on the desktop called "BurnInStatic". Open it.
 - If this folder is missing, there is a backup copy located at \\Villard\SharedFiles\itsiao
- 1) Navigate to "BurnInStatic\source \ 1419SeeeduinoFirmware" and open _1419SeeeduinoFirmware.ino
- 2) Ensure the Seeeduino is connected to the computer via USB.
- 3) Click "Tools>Board>Arduino Mega (ATmega1280)"
- 4) Click "Tools>Serial Port>COM6"
 - If the board is not detected, try another COM port or check with Device Manager.
- 5) Click "File>Upload" and wait for the progress bar to finish. The status should say "Done Uploading"
- 6) Close the application by using "File>Quit"