
M E 325 Exam 1 Problem 3

Group 6


Parker Wilson, Preston Witte, Mike Lawlor, Justin Merkel

The loading spectrum for a machine component is shown below. Assume the part has a cross-sectional area of 0.1in^2 . The fatigue strength S_f , of the part's material is 100 kpsi at 50,000 stress cycles and 60 kpsi at 10^6 cycles. The ultimate tensile strength, S_{ut} , of the part's material is 150 kpsi. The single block shown occurs over a time of 5 seconds. Use the Gerber Failure Criterion to determine the value of σ_{e_a} .

```
A = 0.1; % area in^2
S_f_50000 = 100; % kpsi
S_f_1million = 60; % kpsi
S_ut = 150; % kpsi
```




```
figure;
% Shading of first pass
hold on;
% Curve
plot(x_o, y_o, 'k', 'LineWidth', 2)
% Cycle #1 shading
x_1 = [x_0(3), x_0(4), (x_0(4)+x_0(5))/2];
y_1 = [y_0(3), y_0(4), y_0(3)];
fill(x_1, y_1, 'g');
% Cycle #2 Shading
x_2 = [x_0(6), x_0(7), 2.8];
y_2 = [y_0(6), y_0(7), y_0(6)];
fill(x_2, y_2, 'g');
% Cycle #3 shading
x_3 = [x_0(8), x_0(9), 3.67];
y_3 = [y_0(8), y_0(9), y_0(8)];
fill(x_3, y_3, 'g');
% Cycle #4 shading
x_4 = [x_0(11), x_0(12), 4.68];
y_4 = [y_0(11), y_0(12), y_0(11)];
fill(x_4, y_4, 'g');
```



```
figure;

% Shading of second pass
% Curve
x_2nd = [x_o(1), x_o(2), x_o(5), x_o(10), x_o(13)];
y_2nd = [y_o(1), y_o(2), y_o(5), y_o(10), y_o(13)];
hold on;
plot(x_2nd, y_2nd, 'k', LineWidth=2);


% Cycle #5 Shading
x_5 = [x_2nd(2), x_2nd(3), 2.82];
y_5 = [y_2nd(2), y_2nd(3), y_2nd(2)];
fill(x_5, y_5, 'r');
```



```
figure;

% Shading of third pass
x_3rd = [x_2nd(1), x_2nd(4), x_2nd(5)];
y_3rd = [y_2nd(1), y_2nd(4), y_2nd(5)];
hold on;
plot(x_3rd, y_3rd, 'k', LineWidth=2);

% Cycle #6 Shading
fill(x_3rd, y_3rd, 'b');
```



```
figure;
```

Determine Basquin Parameters (from sf values)

a = 632.7876

b = reduced(2, 3)

```
% Create an augmented matrix for the linearized system of equations for the
% basquin parameters
Aug = [1 \log 10(50000) \log 10(S_f_50000); \dots]
        1 log10(1e6) log10(S_f_1million)]
Aug = 2 \times 3
   1.0000
            4.6990
                      2.0000
   1.0000
             6.0000
                      1.7782
% convert augmented matrix to reduced row echelon form
reduced = rref(Aug)
reduced = 2 \times 3
   1.0000
                     2.8013
                 0
            1.0000
                   -0.1705
a = 10^reduced(1, 3)
```

b = -0.1705

See Attached excel sheet for cycle table with hours to 100% damage