









Parts List			
Reference	Quantity	Description	
1	1	Main PCB	
2	2	M3 8mm screw	
3	1	Laser-Cut Base	
4	1	9V Battery	

Blinking Ornament - Exploded Assembly

Jamal Bouajjaj	Dec 2019
UNH Makerspace	377

4