









NOTE:
- PS_HOLD pulled up to V2.8 to allow for

production programming when chip is blank After programming, the firmware can pull the PS_HOLD low to shutdown the LDO







