

```


.MEAS AC BP_MAX max mag(V(BP_1))    measure peak gain
.MEAS AC BP_RAW_MAX max mag(V(BP_RAW))
.MEAS AC BP_MAX_2 max mag(V(BP_2))
.MEAS AC freq3db WHEN V(BP_1) = BP_MAX*0.707  measure gain at fc
.meas ac LP_MAX MAX mag(V(LP))
.meas ac LP_CUTOFF when db(V(LP)) = -3.0173686494165

```

```

audio I/O testing
.lib opamp.sub
.wave out.wav 16 44100 V(out)
.tran 10s

```



optional divider
 for testing purposes
 (audio I/O testing ltspice directives)