ContiConnect (Fleet Analytics Portal) - PW Test Case #14305

Basic Functional Test for BAT

11/03/2017 11:04 AM - Vigneshwar Kalyanasundaram

Status:	New	% Done:	96%
Priority:	Normal	Spent time:	0.00 hour
Assignee:			
Test_ID:		Business_Process:	
Module:		Business_Area:	

Description

Preparation

- Prepare a working YR that is recognized on the test environment
- Prepare 6 sensors & a mechanism for the sensors to send alerts (special sensors / pump bottle setup)
- Prepare an HHT file with the IDs of these 6 sensors with S2-D4 configuration
- Prepare another HHT file with the IDs of these 6 sensors with a T2-T2-T2 configuration
- Prepare two independent web browser environments on your PC using different browsers / incognito / different machines etc.
- One of these environments will be used for Admin activities & the other will be used for User activities

Steps

- · Log in as an CKU into the Admin environment
- Go into User Management and find an account "X" in a non-English & non-German market that is not shared with ContiOnlineContact.
- In this market, find a fleet that is linked to an SAP account (starting with 7xxx)
- Create a fleet level portal user for this depot & permissions to create vehicles (User "A")
- Go into User Management and find an account "Y" that is integrated with ContiOnlineContact for the USA
- Find an depot such that the Depot ID = Fleet ID
- Create a new portal user with no access to vehicles below the depot level (User "B")
- Create a workshop view user (User "C")
- Assign the YR to a depot in customer "Y" and set to Active.
- Go to Vehicles tab in the Administration area and create a new Bus "U" in depot "X" with an S2-D4 configuration.
- Set the vehicle to "Show & Pay" as billing option
- Set the RCP to appropriate values so that the 6 sensors that are prepared will send urgent and minor alerts.
- Set the units to BAR and Celsius
- In the User environment browser, log in with the credentials of User "A"
- Verify that the vehicle "U" that was created is visible to the user
- Upload HHT file for the 6 sensors to this vehicle
- Create 2 recipients with different languages to receive SMS and Email to this vehicle (ensure we use external email addresses non Conti email)
- Ensure that the vehicle receives alerts and updates continuously from the sensor.
- Check for toasts in the user environment
- · Check if SMSes and Emails are received with correct pressure & temp units in the correct languages
- In the admin environment, go to Vehicles tab in the Administration area and create a new trailer "V" in depot "Y" with an T2-T2-T2 configuration.
- Set the vehicle to "Show & No Pay" as billing option
- Set the RCP to appropriate values so that the 6 sensors that are prepared will send urgent and minor alerts.
- Set the units to PSI and Fahrenheit
- In the User environment browser, log in with the credentials of User "B"
- Verify that the vehicle "V" that was created is visible to the user in the myFleet view
- Upload HHT file for the 6 sensors to this vehicle
- Create 2 recipients with different languages to receive SMS and Email to this vehicle (ensure we use external email addresses nonConti). In this step ensure one receives only SMS and one receives only Email.
- Ensure that the vehicle receives alerts
- Check for toasts in the user environment
- Check if SMSes and Emails are received with correct pressure & temp units in the correct languages

07/24/2018 1/4

- In the user environment, log out and log in with User "C"
- Ensure that the workshop view shows the vehicle status correctly
- Ensure that the birdview and the alerts are correctly visible

Items not covered, but could be added in near future

- Mobile device browser testing
- Testing of vehicle creation & editing with User "A"
- Testing of dashboards & pressure history
- Testing of CITE functionality (label editor, user manuals, password policy etc.)

Subtasks:

Subtasks:	
PW Epic # 14345: Conti Connect R11/17 IT Tests	Closed
PW Test Case # 14346: Admin: Create new Vehicle	Passed
PW Test Case # 14352: Admin: Create new Vehicle (PSI / Fahrenheit)	Passed
PW Test Case # 14354: User: Test Alert Notifications (Trailer)	Passed
PW Bug # 14357: Depotmanager issues	Closed
PW Bug # 14358: Recipient: no Email or SMS	Closed
Bug # 14406: Change recipient Name does not get UI updated	Closed
PW Test Case # 14356: Workshop view user	Passed
PW Bug # 14587: Reloading page problem	Rejected
PW Task # 14359: Test Preparation	Closed
PW Test Case # 14361: Observation List – Update of new observations	Passed
PW Bug # 14372: No update of KPI	Closed
PW Test Case # 14369: KPIs: noAdmin, myFleet	Passed
PW Test Case # 14373: KPIs: Admin, myFleet	Passed
PW Bug # 14404: Wrong KPI Numbers	Rejected
PW Test Case # 14384: Observation List – Update of changed observations	Passed
PW Bug # 14378: Change of Observation to stable	Closed
PW Test Case # 14385: Sensor data available - normal user	Passed
PW Test Case # 14386: Observation List – Update of deleted observations	Passed
PW Bug # 14371: Deleted Observation	Closed
PW Test Case # 14422: Show / No-Show vehicle in Portal - Admin Check	Passed
PW Test Case # 14423: Show / No-Show vehicle in Portal - NoAdmin Check	Passed
PW Bug # 14426: Sensor inconsistency	Closed
PW Test Case # 14538: Fleet Hierarchy authorization	Passed
PW Bug # 14539: Dashboard Hierarchy authorization	Closed
PW Bug # 14540: "Benachrichtigungen" hierarchy authorization	Closed
PW Test Case # 14542: MyFleet update	Passed
PW Bug # 14545: MyFleet: List is not updating	Rejected
PW Bug # 14546: Vehicle of vehicle list chages from red to green	Rejected
PW Bug # 14547: FA-SENSORRESULT is slow	Rejected
PW Test Case # 14549: Check "Historic Report" in detailed view	Passed
PW Bug # 14557: History issue of Dashboard	Closed
PW Bug # 14558: Missing Translation	Rejected
PW Bug # 14559: Missing translation (french)	Rejected
PW Bug # 14565: Pressure History: period=last week	Rejected
PW Bug # 14566: Pressure History: period=last 24 hours	Rejected
PW Bug # 14568: Vehicle search issue	Closed
PW Test Case # 14572: Historic Report - bar check	Passed
PW Test Case # 14573: Historic Report - psi check	Passed
PW Bug # 14575: HHT upload issue	Closed
PW Test Case # 14578: HHT upload	Passed
PW Bug # 14583: Fa.observation service - No space left on device	Closed
PW Test Case # 14584: Delete recipien with no assignments	Passed
PW Defect # 14585: Deleting of recipient issue	Closed

07/24/2018 2/4

PW Test Case # 14586: Delete recipien with assignments	Passed
PW Defect # 14593: NoAdmin User: Creating and editing of vehicles incositanc	Closed
PW Test Case # 14604: Create recipien as fleet user & delete it with depot user	Passed
PW Defect # 14605: Workshop View: Vehicles disappears suddenly	Closed
PW Epic # 14407: BAT R11/17 Business Tests	New
PW Test Case # 14408: Admin: Create new Vehicle	Passed
PW Test Case # 14409: Admin: Yard Reader assignment	Passed
PW Test Case # 14410: User: Test Alert Notifications	Passed
PW Test Case # 14411: Admin: Create new Vehicle (PSI / Fahrenheit)	Passed with Rese
PW Bug # 14544: "Others" not available as a Vehicle Make for Bus	Rejected
PW Test Case # 14412: User: Test Alert Notifications (PSI / Fahrenheit)	Passed
PW Test Case # 14413: Workshop view user	Testing Phase
PW Bug # 14570: Workshop View not loading vehicles correctly	Closed
PW Test Case # 14414: Observation List – Update of new observations	Passed with Rese
PW Bug # 14550: RCP not visible to customer despite low pressure alerts	Closed
PW Test Case # 14415: Observation List – Update of changed observations	Passed with Rese
PW Bug # 14548: Low Pressure Alerts but no Pressure displayed	Rejected
PW Test Case # 14416: Observation List – Update of deleted observations	Passed
PW Test Case # 14418: KPIs: noAdmin, myFleet	Testing Phase
PW Test Case # 14419: KPIs: Admin, myFleet	Testing Phase
PW Test Case # 14420: Sensor data available - normal user	Passed
PW Bug # 14553: Wrong text after editing in label editor	Closed
PW Test Case # 14424: Show / No-Show vehicle in Portal - Admin Check	Passed
PW Test Case # 14425: Show / No-Show vehicle in Portal - NoAdmin Check	Passed
PW Bug # 14541: Get Customer Data from SAP does not return customer details in User Man	New
PW Bug # 14543: Missing options in CITE for US-360FS User	Closed
PW Bug # 14554: Email notification missing	Closed
PW Bug # 14555: Test HHT file does not work	Closed
PW Bug # 14579: Cannot set vehicle to Inactive	Closed
PW Bug # 14588: Some passwords are not working	Closed
PW Bug # 14589: Inactive Vehicle is sending toasts, SMSes and Emails	Closed
PW Bug # 14590: KPI tiles unreliable	Closed
PW Bug # 14576: Logout button does not work	Closed
PW Epic # 14609: BAT R11/17 Business Retest	New
PW Bug # 14608: Vehicle List & Alert List do not load (QA)	Closed
PW Bug # 14610: Invalid Sensor IDs found (Inconsistent/old Testdata)	Rejected
PW Bug # 14611: False urgent alerts shown in alerts view that turn green when extended	Closed
PW Story # 14613: KPI Tile values are incorrect (Business Logic Enhancement)	Testing Phase
PW Bug # 14653: False urgent alerts shown in alerts view that turn green when extended	Rejected
PW Bug # 14679: Portal does not load data (26.11)	Closed
PW Bug # 14649: Workshop View: Workshop List: Vehicle shows yellow alert when bird view	Closed
PW Bug # 14657: Missing Vehicles in PROD (OK in Admin, missing in Portal)	Rejected
PW Bug # 14670: Translations do not currently work	Closed

03/09/2018 Copied to BAT4 - PW Test Case #15358: Basic Functional Test for BAT - Group 1 11/07/2017 New

History

#1 - 11/03/2017 11:05 AM - Vigneshwar Kalyanasundaram

- Description updated

#2 - 11/03/2017 11:06 AM - Vigneshwar Kalyanasundaram

- Description updated

3/4 07/24/2018

#3 - 11/03/2017 12:14 PM - Vigneshwar Kalyanasundaram

- Description updated

#4 - 11/03/2017 12:16 PM - Vigneshwar Kalyanasundaram

- Description updated

#5 - 11/03/2017 12:54 PM - Vigneshwar Kalyanasundaram

- Description updated

#6 - 11/07/2017 10:07 AM - Vigneshwar Kalyanasundaram

- Description updated

#7 - 01/05/2018 07:35 AM - Vigneshwar Kalyanasundaram

- Copied to PW Test Case #15358: Basic Functional Test for BAT - Group 1 added

07/24/2018 4/4