ContiConnect (Fleet Analytics Portal) - PW Test Case #14542

PW Test Case # 14305 (New): Basic Functional Test for BAT PW Epic # 14345 (Closed): Conti Connect R11/17 IT Tests

MyFleet update

11/13/2017 01:25 PM - Alexandros Efthymiadis

Status: Passed % Done: 100%

Priority: Normal Spent time: 0.00 hour

Assignee: Alexandros Efthymiadis

Test_ID: Business_Process:

Module: Business Area:

Description

Prerequisite:

- 1. Log in System using the user: "TC_User_A" pw: "MHP_User_A_2017!"
- 2. Search for the vehicle "TC_BUS_01"
- 3. Open the Vehicle Détails
- 4. Click on Editer and than on Télécharger le fichier HHT

Steps:

- 1. Go back the tab where the vehicles are listed(MaFlotte)
- 2. Search for the vehicle you can manipulate the pressure so you can see it in the list (TC BUS 01)
- 3. Release the pressure

Expect:

The MaFlotte list should after a refresh update depanding on how much pressure you changed. Also toast should appear

Subtasks:

PW Bug # 14545: MyFleet: List is not updating Rejected

Related issues:

Copied to BAT4 - PW Test Case #15393: MyFleet update Testing Phase

History

#1 - 11/13/2017 02:08 PM - Alexandros Efthymiadis

- Description updated

#2 - 11/14/2017 09:33 AM - Alexandros Efthymiadis

- Description updated
- Status changed from New to Accepted

#3 - 11/14/2017 09:34 AM - Alexandros Efthymiadis

- Status changed from Accepted to Ready for Test

#4 - 11/14/2017 09:36 AM - Alexandros Efthymiadis

- Status changed from Ready for Test to Passed

successfully tested.

#5 - 01/05/2018 07:36 AM - Vigneshwar Kalyanasundaram

- Copied to PW Test Case #15393: MyFleet update added

07/27/2018 1/1