



04b - Hemera Tool Dock Assembly

Written By: Greg Holloway




Step 1 — Parts.



- Print the Dock parts linked below.
- https://github.com/e3donline/ToolCha nger


Step 2 — Screw.





Affix the pritned bracket to the Motion System.


Step 3 — Underside.





Secure the bracket from the underside.


Step 4 — Dock.





- Affix the dock to the bracket.
- For instructions of to assembly the dock see | 04a V6 Tool Dock Assembly.

Step 5 — Hemera.



Place the Hemera Tool onto the docks.