


UBOR-JAVA R01 / Электроника

141 компонент · 100 именованных цепей · 8 дочерних схем KiCad. Вид PDF построен из канонического графа соединений, не экспортирован приложением KiCad.


UBOR-JAVA R01 / потоки управления



СТАТУС: структурная проверка выполнена. KiCad не запускался; ERC, PCB, DRC и SPICE не выполнены. Условные модульные разъёмы не являются готовыми footprint. Силовой выпуск запрещён до проверки рекуперации, тепла, предзаряда и выбранных компонентов.


Power / battery / precharge / motor contactor

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.




Hardware watchdog and edge-triggered manual rearm

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.




Raspberry Pi header and byte buses / 3.3V logic only

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.




Dry-contact safety sensing / beam inputs / range output

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.




DRV8874 channel 0: left

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.




DRV8874 channel 1: right

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.



DRV8874 channel 2: brush

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.



DRV8874 channel 3: belt

R01 / canonical connection graph. KiCad ERC and PCB routing NOT performed.

