Tool Sign-Out Sheet

Operations:

Sign-Out Operation - Once the operator enters the tool number, their initials, the dash number if possible, and their workstation number, the program searches the entire workbook except for the "Sign-Out-Log" and "Tool_Checkout" sheet, and copies them to the "Tools Currently In Use" table.

Sign-In Operation - After the operator enters the tool number, the dash number if possible, and their initials, the program searches the table for those values and copies them to the "Sign_Out_Log" before removing them.

Clear Log File - This operation automatically clears the log sheet.

Additions:

- Input values follow strict formats, preventing operators from entering incomplete or incorrect values.

Example for tool:	Letters-Letters-Numbers.	TEI-C-100.
Example for Initial:	*2 Letters*	*EM.*
Example for dash number:	*-Numbers*	*-12*
Example for workstation:	*2 Letters - Numbers*	*WS-23*

- Messages will be displayed when the format doesn't match, and will identify which input was incorrect.
- Number of Log entries are tracked, with a maximum of 100.
- Added tracker for amount of tools due for calibration.