## **AQL CHART**

Office 909, 9<sup>th</sup> Floor, Jintian Building, 1199 Heping Road Luohu, Shenzhen, Guangdong, China 深圳市罗湖区和平路1199号金田大厦9楼909室, 邮编: 518010 PH: +86 755-2220-0833



www.asiaqualityfocus.com

Acceptable Quality Levels (Normal Inspection)																											
pple Code fer pple		0.065		0.1		0.15		0.25		0.4		0.65		1		1.5		2.5		4		6.5		10		15	
Sample Size Code Letter	Sample Size	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re	Ac	Re
Α	2																			,	$\downarrow$	0	1				7
В	3																	,	,	0	1	4	1		,	1	2
С	5																<u>,                                      </u>	0	1	4		•	ļ	1	2	2	3
D	8													•	7	0	1	4			<b>↓</b>	1	2	2	3	3	4
Е	13												,	0	1	4		•	<u> </u>	1	2	2	3	3	4	5	6
F	20									•	,	0	1	4		•	<b>/</b>	1	2	2	3	3	4	5	6	7	8
G	32							•	7	0	1		<b>\</b>	•	,	1	2	2	3	3	4	5	6	7	8	10	11
Н	50					•		0	1	4		•	7	1	2	2	3	3	4	5	6	7	8	10	11	14	15
J	80			•	,	0	1	4		•	Į.	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22
K	125		,	0	1	4		•	,	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22		_
L	200	0	1	4		•	<u> </u>	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22				
М	315			•	,	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22						
N	500	4	,	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	4	<b>†</b>						
Р	800	1	2	2	3	3	4	5	6	7	8	10	11	14	15	21	22	4									
Q	1250	2	3	3	4	5	6	7	8	10	11	14	15	21	22	4											
R	2000	3	4	5	6	7	8	10	11	14	15	21	22	4													

♦ = Use first sampling plan below the arrow. If sample size equals, or exceeds, lot or batch size, do 100% inspection.

 $\uparrow$  = Use first sampling plan above the arrow.

For a complete explanation of AQL see: The Importer's Guide to Managing Product Quality with AQL

## **AQL CHART**

Office 909, 9<sup>th</sup> Floor, Jintian Building, 1199 Heping Road Luohu, Shenzhen, Guangdong, China 深圳市罗湖区和平路1199号金田大厦9楼909室, 邮编: 518010 PH: +86 755-2220-0833



www.asiaqualityfocus.com

## SINGLE SAMPLING PLAN FOR NORMAL INSPECTION, ANSI/ASQ STANDARD Z1.4-2003

## **SAMPLE SIZE CODE LETTERS**

1.5	Gen	eral Inspection Le	evels	Special Inspection Levels						
Lot Size	I	II	III	S1	\$2	\$3	\$4			
2 to 8	А	А	В	А	А	А	А			
9 to 15	А	В	С	А	A	А	А			
16 to 25	В	С	D	А	А	В	В			
26 to 50	С	D	E	А	В	В	С			
51 to 90	С	E	F	В	В	С	С			
91 to 150	D	F	G	В	В	С	D			
151 to 280	E	G	Н	В	С	D	Е			
281 to 500	F	Н	J	В	С	D	E			
501 to 1200	G	J	K	С	С	E	F			
1201 to 3200	Н	K	L	С	D	E	G			
3201 to 10000	J	L	М	С	D	F	G			
10001 to 35000	K	М	N	С	D	F	Н			
35001 to 150000	L	N	Р	D	Е	G	J			
150001 to 500000	М	Р	Q	D	Е	G	J			
500001 and over	N	Q	R	D	E	Н	K			

For a complete explanation of AQL see:

The Importer's Guide to Managing Product Quality with AQL