EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 CERTIFIED COMPANY
Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

Part A - Revision Questions

1. In SMAW, what provides Physical shielding for the weld pool?

   A. Flux
   B. Slag
   C. Electrode holder
   D. Earthling clamp

2. where is the IQI usually placed?

   A. Film side.
   B. Source side.
   C. Between screen and Film.
   D. On the internal diameter.

3. What will directly affect the cooling rate of the weld pool?

   A. Welding process.
   B. Metal size.
   C. Electrode polarity.
   D. Electrode diameter.

4. What of the following is considered a radiation source in RT?

   A. Barium xxx
   B. Iridium 192
   C. Uranium xxx
   D. Cadmium xxx

5. In FCAW Process, what will increase feed speed result at the Current when all other variables held Constant?

   A. Increase the current and then penetration
   B. Decrease the current and then penetration
   C. Increase the current and then spatter
   D. There is no relation between feed speed results at the Current

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
uhmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01220969214

6. The Capabilities of The CWI is specified in which of the following specification?

   A. AWS B5.1
   B. AWS 5.4
   C. AWS 5.2
   D. QC1

7. The short arc welding is used to achieve all of the following, except ….?

   A. Better Shielding
   B. High disposition rate
   C. Reduce Undercut
   D. Reduce Arc blow

8. Increasing Arc length In FCAW Process will …….

   A. Increase Spatter
   B. Consume shielding Gas Faster
   C. Increase Penetration
   D. decrease penetration

9. Which Electrode Classification Designate Shielding gas Contain (75% Argon, 25% CO2), so that be applicable for usage in Vertical welding position?

   A. E70T-1M
   B. E71T-1M
   C. E70T-1
   D. E71T-1

10. A CWI can disclose a WPS of a former employer if:

    A. A consent has been written to the Former employer
    B. A consent has been received from the present employer
    C. The WPS is a SWPS
    D. A consent sent to the AWS

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

11. what is the difference between weld symbol and welding symbol?

A. Weld symbol is a part of Welding symbol.
B. Welding Symbol is a part of Weld symbol.
C. Welding Symbol and Weld symbol is the same thing.
D. Welding Symbol is a part of Weld symbol.


12. Which symbol is always shown below reference line?

A. Edge weld
B. Melt Through
C. Surfacing weld
D. Fillet weld

13. Which of the Following indicates side information in a welding symbol?

A. Arrow
B. reference line
C. weld symbol

14. In the welding symbol shown, "5/16" Refer to?



A. Arc spot depth of penetration
B. Arc spot Diameter.
C. Number of blugs.
D. Pitch between blugs.

15. Porosity is usually encountered in ……?

A. Casting steel.
B. Rolled steel.
C. Brazing.
D. Extruded pipes.

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 CERTIFIED COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

16. Bending test can be done by which of the following machines?

A. Hammer
B. Double Action Tensile Test Machine.
C. A lathe machine
D. A planer machine

17. Is "Fit-up" is important stage for fillet welds?

A. No, welds can compensate
B. No, Fit-up not need for Fit-up
C. Yes, to make sure that Effective throat is lesser than theoretical throat.
D. Yes, to make sure that Effective throat is greater than theoretical throat.

18. What is the cooling rate of weldment per ◦f/hr., if the temperature of the weldment was 1200 ◦f then dropped to1100 ◦f after one-half hour during the in-process welding?

A. 1200 ◦f/hr.
B. 12 ◦f/hr.
C. 120 ◦f/hr.
D. 200 ◦f/hr.

19. If it is a variable in the "WPS" that the bevel angle = 37◦±2.5, which of the following ranges considered acceptable?

A. Θ= 35◦:39◦
B. Θ= 30◦:39◦
C. Θ= 35◦:49◦
D. Θ= 15◦:39◦

20. if the base metal actual thickness = 0.75 inch and the qualified thickness range are (T/2: 1.5T). Which of the following ranges considered acceptable?

A. T=0.375:1.125 inch.
B. T=0.475:2.125 inch.
C. T=0.325:1.155 inch.
D. T=0.175:1.195 inch.

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 CERTIFIED COMPANY
Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

21. During production welding the GMAW Welding machine consumed filler metal with length of 12 inch in 10 sec. what is the consumed length in one minute?

A. 12 inch
B. 74 inch.
C. 72 inch
D. 79 inch


12 in → 10 sec
→ 60

12 × 6 = 72

22. The mating surfaces of a member that is in contact with or in close proximity to another member to which it is to be joined.

A. faying surfaces
B. back weld
C. surfacing weld
D. source side

23. The sketch below is a specimen for:



A. Bend Test
B. Tensile Test
C. Charpy V notch Test
D. Neck Break Test

24. For alloy materials what is the minimum percentage of Chromium to be contained in order to classify as a Stainless-steel alloy?

A. 12%
B. 3%
C. 4%
D. 17%

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

25. a joint root condition in a groove weld in which weld metal doesn't extend through the joint thickness.

(A) Incomplete joint penetration
B. Root Face
C. Backing weld
D. Build up

---

26. A welder qualified by a performance qualification test using GMAW-S. Is this welder qualified to use FCAW in production weld?

A. Yes.
(B) No.
C. Yes, but only FCAW-S.
D. None of the above

---

27. What is the most common Defect occurring at /adjacent the weld toe?

A. Burn through
(B) Overlap
C. Incomplete penetration
D. Slag inclusions

---

28. For Visual inspection what is the suitable tool / method to inspect welds located at narrow zones or small pore pipes?

A. Protective gloves
B. Safety Googles
(C) Mirror /Borescope
D. WAC gage

---

29. The carbon equivalent unit is employed to predict the tendency to form which of the following:

A. Lamellar Pearlite
B. Upper Bainite
(C) Martensite

CamScanner

Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.hoghaldy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

D. Austenite


30. The mood of transfer axial spray In GMAW Welding process essentially require which of the following:

A. specific argon ratio
B. specific current polarity and value.
C. Special torch
D. Specific filler metal classification.

31- What is the essential difference between FCAW-S and FCAW-G?

A. The presence of core wire filler metal
B. The presence of shielding gas
C. The type of the power source.
D. The type of current and polarity


32-What is the first operation specified in the below figure?



A. Conduct MT
B. Back-Gouge
C. Weld the U groove
D. Weld the V groove
E. Conduct CJP


EWS
QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

33. What is the last operation specified in the below figure?



A. Conduct MT
B. Back-Gouge
C. Weld the U groove
D. Weld the V groove
E. Conduct CJP

34. where is MT VT Performed as specified in the below figure?



A. On the V-groove face surface
B. On the V-groove intermediate surface
C. On the back gouged surface..
D. On the finish weld V-groove weld surface
E. On the finish weld U-groove weld surface

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

35. when using welding symbol for brazing process contained fillet weld, what is the required data for fillet weld symbol to be identified?

A. Convexity height
B. fillet weld size
C. root opening
D. pitch and length

36. What is the difference between incomplete penetration and incomplete fusion?

A. IF is associated with root, while IP could be in any other section in weld.
B. IP is associated with root, while IF could be in any other section in weld.
C. IP and IF have the same meaning
D. none of the above

37. In the SMAW electrode designation E 308L, what does the designator 308 signify:

A. Lime coating
B. Alloy type
C. Tensile Strength
D. Hydrogen content
E. Welding Position

38. What does the prefix "ER" indicate in the ER 309L filler metal classification?

A. The electrode is in a rolled from
B. It can be used as an electrode or rod
C. It is for rust-resistant applications
D. It is intended for reverse polarity application.

39. FCAW electrode classification uses the letter "T" TO INDICATE which of following electrode constructions?

A. Tungsten
B. Tubular
C. Tantalum
D. Thorium

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

E. Titanium

40. Which of the following material required preheat to accomplish sound weld?

A. low alloy
B. mild steel
C. high carbon
D. Thorium
E. Titanium

41. The material contains carbon content more than ..... % shouldn't be weld without preheat and post heat because of its low weldability.

A. 50%
B. 0.3%
C. 1%
D. 12%

42. what is the function of the "two side copper plates" in ESW process?

A. Joint preparation requirement
B. tracking the filler metal
C. Enhance the mechanical properties.
D. None of the above.


43. Which of the following is nonstandard term regarding to AWS A3.0 Definitions?

A. Caulk
B. Seal
C. Back weld
D. Fillet weld

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

44. The symbol in Figure below requires what kind of the testing?



(A) Penetrant testing on the other side of part and all around the weld
B. Proof testing on the other side of the part
C. Penetrant testing on the arrow side of the part.
D. Proof testing on the arrow side of the part
E. Penetrant and radiographic testing from the other side

45. Which is more sensitive for detecting subsurface flaws and small discontinuities in large thicknesses?

A. RT
(B) UT
C. MT
D. PT

46. In SMAW, covered electrode holder is sized or rated according to which of the following?

A. The welder hand size.
B. The power source polarity
(C) The maximum current
D. The electrode size

47. In GTAW normally shielding gas is .....?

A. Argon +Hydrogen
B. Argon + very small amount of oxygen
→ C. Helium + Argon
D. Nitrogen

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

48. What does the supplementary symbol in the figure below?



A. Laser radiation
B. Neutron radiation source
C. Phased array
D. Radiation direction
E. Oblique lighting

49. The symbol is always placed below the reference line is?


A. stud weld
B. fillet weld
C. profile contour
D. back weld.

50. Which of the following is true regarding air carbon arc cutting?

A. Metal removal is accomplished by an oxygen stream
B. Cutting is accomplished by metal oxidation
C. It is capable of cutting metals that cannot be cut by the oxyfuel gas cutting process.
D. None of the above.


CamScanner

Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024



51. The number 1 in the above figure represents which of the following?


A. Weld convexity
B. Weld face
C. Weld root Reinforcement.
(D) Weld Face Reinforcement
E. Weld backing



52. The number 2 in the above figure represents which of the following?


A. Weld convexity
(B) Weld root
C. Weld root Reinforcement.
D. Weld Face Reinforcement
E. Weld backing

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024



53. The number 3 in the above figure represents which of the following?

A. Weld convexity
B. Weld root
C. Weld root Reinforcement.
(D) Weld Face Reinforcement
E. Weld backing



54. The number 4 in the above figure represents which of the following?

A. Weld convexity
B. Weld root
C. Weld root Reinforcement.
D. Weld Face Reinforcement
(E) Back weld

55. A200 Amp power supply of 60% duty cycle what is the minimum time in minutes will it operate at 200 Amp?

A. 1 minutes
(B) 6 minutes

CamScanner

Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

C. 10 minutes
D. 60 minutes

56. Which Electrode Classification Designate Shielding gas Contain (75%Argon, 25%CO2), so that be applicable for usage in flat welding position?

(A) E70T-1M
B. E71T-1M
C. E70T-1
D. E71T-1

57. When using oxyacetylene with mild steel the flame should be?

A. Carburizing.
(B) Neutral
C. Oxidized
D. Reducing

mild steel, low Carbon steel, Al, Cast iron → Neutral
High Carbon steel, Nickle → Carburizing
Brass, Bronze, Brincall-4 → Oxidized

58. In SMAW, covered electrode holder is sized or rated according to which of the following?

A. The welder hand size.
B. The power source polarity
(C) The maximum current
D. The electrode size

59. What cannot be determined with metallographic?

A. Depth of weld penetration
B. Number of weld passes
(C) Weld of ductility
D. None of the above

60. The number 4 in figure 14 represents which of the following?

Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024




Figure 14

A. Beads
B. weld root
C. weld toe
D. face reinforcement

61. Electrodes for GTAW are different from other welding processes in which of the following ways?


A. They are non-consumable
B. They are autogenous
C. They can be tubular or solid
D. They contain flux
E. They do no contribute to conductivity

62. Which of the following is the most accurate regarding the selection of a filler metal of GTAW application

A. GTAW electrodes are not consumed in the GTAW process
B. AWS not specified the selection of filler metal in GTAW
C. Generally, filler metals are selected to match the properties of the base metal in the welded condition
D. Reaction between filler metal and shielding gas is very important
E. Because of tungsten, in GTAW process filler materials do not clean like other process


Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.hoghaldy@ewsonline.net
Mob-1: 002 - 01009472812 Mob-2: 002 - 01205902024

63. Which welding symbol represents an Intermittent Fillet Weld?



A. 1
B. 9
C. 4
D. 7
E. 6

64. The number #1 in the below figure represents which of the following?



A. Depth of fusion
B. Depth of penetration
C. Fusion face
D. Weld interface

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

65. When the weld structure is to be examined at magnification of 10x or lower, what kind of specimens are used?

(A) Macro specimens
B. Micro specimens
C. Tensile specimens
D. Charpoy specimens

---

66. Which of the following they may minimize slag entrapment?

A. changing the electrodes types
B. thorough stag removal between passes
C. proper bead placement
(D) only B and C above

---

67. What is the proper term for the boundary between weld metal and base metal?

A. Fusion face
(B) Weld interface
C. Groove face
D. Fusion interface

---

68. Which of the following statements is correct regarding magnetic particle testing?

A. It is sensitive enough to readily detect deep subsurface discontinuities
B. It can be performed on all types of materials, ferrous and non-ferrous
C. Subsurface discontinuities are easily seen and interpreted with this method
(D) Subsurface discontinuities near the surface may be observed, but they may not be Cleary defined

---

69. GTAW can be used to weld most metals, which of the following is most useful

A. Galvanized Parts
(B) Thin Gauge Aluminum
C. Reinforcing rod
D. Heavy Steel Plate

CamScanner

Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghdly@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

70. In which of the following ways are fluxes for SAW classified according to the manner in which they modify the composition of the weld metal?

A. Oxidizing or reducing
B. Fused or agglomerated
C. Granular or powdered
D. Neutral, active, or alloy
E. Covered or self-shielded

71. An ultrasonic test of a plate shows a trace on the CRT with peaks as shown in below figure. If the sweep is from left to right, the peak at (2) may indicate ------.




Figure 13

A. A flaw at the surface
B. A flaw near the center
C. A reflection from the back
D. A flaw at the back
E. There is no flaw indicated on the trace

72. A stress relief heat treatment {approximately 1150 F (620 C) on carbon steel} is intended to accomplish which of the following?

A. Change the microstructure of the weld
B. Increase the tensile strength of the weld
C. Reduce the residual stress across the weld
D. Increase the impact strength of the weld
E. Provide a method of oven heating for the removal of gas poke strapped in the weld

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 CERTIFIED COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

73. Brazed joints can be tested by which of the following testing methods

A. UT
B. Leak
C. Torsion
D. All of The Above
E. Only A and C above

---

74. be classified as brazing, the joining process must use a filler metal wire which of the following characteristics?

A. The filler metal cannot wet the surfaces to be joined
B. The filler must melt at above 840 F
C. The filler metal must melt in an oxidizing atmosphere
D. The filler metal must have acceptable mechanical properties when mixed with the base metal
E. The filler metal must have non-ferrous properties

---

75. Why should inter-pass cleaning be verified?

A. to ensure slag removal
B. to avoid welding over cracks
C. to avoid subsequent porosity
D. to avoid subsequent incomplete fusion
E. All of the above

---

76. Which of the following is an advantage of fluorescent penetrants over visible penetrants?

A. The inspection can be carried out in a well-light area
B. Small indication is more easily seen because it is more sensitive test
C. It can be used where contact with water is objectionable
D. It is less sensitive to contamination of discontinuities.
E. The visible dye requires no vehicle or solvent

EWS QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 - 01009472812 Mob-2: 002 - 01205902024

77. When using oxyacetylene with mild steel the flame should be?

A. Carburizing.
B. Neutral
C. Oxidized
D. Reducing

---

78. Bevel Angle Range 37.5 with tolerance +- 2.5?

A. 36-42
B. 35-40
C. 33-38
D. 35.5-39.5

---

79. Find out Range of 25% of 20.

A. 3
B. 2
C. 5
D. 8

---

80. A welder continuously held for 10 minutes with 60 duty cycle to a complete weld by using 100% duty cycle, how much Minutes it will take?

A. 10 Minutes
B. 6 Minutes
C. 8 Minutes
D. 15 Minutes


---

81. Qualification Range 0.5 to 1.1T. The value of the T is 0.76. What is the range?

A. 0.38 to 0.836
B. 0.46 to 0.789
C. 0.34 to 0.658
D. 0.58 to 0.936

EWS
QUALITY TO THE WORLD
ISO 9001
CERTIFIED ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

82. Which is the correct as shown figure?




A. GTAW
B. SMAW
C. FCAW
D. PAW

83. Typically used radiographic sources in the weld inspection?

A. Cobalt 60
B. Iridium 192
C. X-ray
D. All of the above
E. B & C of the above

84. What is indicate by this symbol?




A. Surface welding
B. Reduce root opening
C. Weld bevel angle
D. Base Metal

85. which one is correct as per this figure?



A. Spot weld
B. Pug weld
C. Flare weld
D. Slot weld

86. This Figure is indicated?



A. Double Bevel groove with plug weld
B. Single V Groove with Plug Weld
C. Double V Groove with Spacer
D. Single Bevel Groove with Spacer

CamScanner

EWS QUALITY TO THE WORLD
ISO 9001
CERTIFIED ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghdy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

87. Which of following best describes electrode classification for CS Electrode for SMAW?

A. Electrode, atomic symbols of the major elements in the electrode in descending order of concentration
B. Electrode, hydrogen content, yield strength of resulting weld metal, and suitable welding position
C. Electrode, chemical composition of undiluted weld metal, suitable welding position, and type of suitable current
D. Electrode, minimum tensile strength, suitable welding position, type of covering and current

E7018

88. Which of the welding techniques describes a welding process in which the filler metal feeding is machine operated while the joint travel speed and guidance are the responsibility of the welder?

A. Manual
B. Semi-Automatic
C. Mechanized
D. Automatic

89. In Plasma Arc Welding, which discontinuity most related below?

A. Slag Inclusion
B. Copper inclusion
C. Overlap
D. Undercut

90. In Electro Slag Welding Copper Shoes are used for?

A. To avoid Slag inclusion
B. To prevent excessive heat of Base metal and block Weld metal
C. To reduce Electrode consumption
D. TO prevent Crack propagation

CamScanner

Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

91. MT can efficiently be done in?

A. Stainless weld on Stainless base metal
B. Carbon steel weld on Stainless base metal
C. Carbon steel weld on Carbon steel base weld
D. None of these

92. In welding sequence, Welds done in both side and the multiple layers is done as Overlapping?

A. Block Sequence
B. Cascade Sequence
C. Split layer
D. Back step sequence

93. Stud welds + Surfacing welds always should be done in?

A. Both side
B. Opposite to weld side
C. Arrow side
D. groove side

94. In Intermittent welds, dimension in the order of?

A. Length, pitch, Size
B. Pitch, Length, Size
C. Size, Pitch, Length
D. Size, Length, Pitch

95. If Preheat has not done on the weld, what will happen below?

E. wider Heat affected zone
F. avoid delayed cracking
G. improves weld quality
H. Narrow heat affected zone

EWS QUALITY TO THE WORLD
ISO 9001
CERTIFIED ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St, Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

96. Porosity is defined as?

A. Linear type of Defect
B. Transverse type of defect
C. defect perpendicular to stress
D. cavity type of Defect

97. Under fill is known as?

A. Excess filling of weld groove
B. Convex shape of reinforcement
C. Complete removal of reinforcement
D. Inadequate filling of weld groove

98. In PT Testing, After Dwell what action will be done?

A. Apply the Penetrant
B. Apply the developer
C. Remove the excess penetrant
D. Cleaning the part

99. Advantages of UT over RT?

A. Both side access needed
B. one side access required
C. calibration required
D. couplant required

100. The substance used in UT to aid in the transmission of sound from the search unit to the work piece and back is called?

A. Solvent
B. Couplant
C. Cable
D. Transducer

CamScanner

EWS
QUALITY TO THE WORLD
ISO 9001
ISO 45001:2018 COMPANY
Egyptian Welding Society
182 Delta St. Sporting. Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed.boghddy@ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

101. In GMAW Welding Process, CO2 is used as shielding gas, because?

A. it has high mixing ratio
B. it has stability in high pressure
C. it has light density
D. it has Low cost and high Penetration.

---

102. NDE technicians are usually qualified in accordance with the requirement of?

A. ASME SECTION IX
B. AWAS D1.1
C. ASME SECTION VIII
D. ASNT SNT-TC-1A

---

103. Which of the following results from improper termination of the SMAW electrode and shrinking of the molten weld pool during welding?

A. incomplete fusion
B. porosity
C. slag inclusion
D. crater crack

---

104. Which NDE test is used to determine the soundness of the weld other than nick break and bend test?

A. UT, RT
B. PT, MT
C. PT, RT
D. MT, UT

---

105. In Electro Slag Welding (ESW) Copper Shoes are used for?

A. Joint preparation requirement
B. To prevent excessive heat of base metal
C. To reduce Electrode consumption
D. To prevent Crack propagation
E. A & B

CamScanner

Egyptian Welding Society
182 Delta St, Sporting, Alexandria
Telefax: 03-5916598
Website: www.ewsonline.net
E-mail: inquiries@ewsonline.net
ahmed boghddy @ewsonline.net
Mob-1: 002 – 01009472812 Mob-2: 002 – 01205902024

106. Typically used radiographic sources in the weld inspection.

A. Cobalt 60
B. Iridium 192
C. X-ray
D. All of the above
E. B & C of the above

---

107. In CAC-A process, Metal removed by?

A. By cleaning after cut
B. By compressed air
C. By wire brush
D. By solvent cleaning

---

108. If a welding inspector feels he or she is not qualified to make judgment as to the acceptability of weldment, he or she should?

A. Allow work to continue because further welder experience will improve quality
B. Wait to make judgment until he or she had time to get additional training
C. Do the best he or she can and report accordingly
D. Call for assistance from someone who is qualified

CamScanner