Measurement and Instrumentation

Theory and Application

characteristics instrument types measurement systems, sensor technologies reliability principles Green Constitution precision bins sensitivity resolution measurement uncertainty calibration environment calluration environment prosourors measuring sensors accelerometers working standard variable conversion elements signal transmission labview oscilloscopes digital computation intelligent devices reliability input-output interface self-calibration Will agonic & ineligen sens Sound coll manager had a few indicators and the second State Land Bernalds Industriance Italianus Capacitive sensor The Achieven States and the States of the St

Alan S. Morris Reza Langari



Contents

Acknou	vledgement	xvii
Preface	·	xix
Chapte	r 1 Fundamentals of Measurement Systems	1
	Introduction	
	Measurement Units	
1.3	Measurement System Design	3
	1.3.1 Elements of a Measurement System	
	1.3.2 Choosing Appropriate Measuring Instruments	
1.4	Measurement System Applications	
1.5	Summary	10
1.6	Problems	10
Chapte	r 2 Instrument Types and Performance Characteristics	11
-	Introduction	
	Review of Instrument Types	
	2.2.1 Active and Passive Instruments	
	2.2.2 Null-Type and Deflection-Type Instruments	
	2.2.3 Analogue and Digital Instruments	15
	2.2.4 Indicating Instruments and Instruments with a Signal Output	16
	2.2.5 Smart and Nonsmart Instruments	16
2.3	Static Characteristics of Instruments	17
	2.3.1 Accuracy and Inaccuracy (Measurement Uncertainty)	17
	2.3.2 Precision/Repeatability/Reproducibility	18
	2.3.3 Tolerance	20
	2.3.4 Range or Span	20
	2.3.5 Linearity	
	2.3.6 Sensitivity of Measurement	
	2.3.7 Threshold	
	2.3.8 Resolution	
	2.3.9 Sensitivity to Disturbance	
	2.3.10 Hysteresis Effects	
	2.3.11 Dead Space	26

2.4	Dynamic Characteristics of Instruments	26
	2.4.1 Zero-Order Instrument	
	2.4.2 First-Order Instrument	28
	2.4.3 Second-Order Instrument	31
2.5	Necessity for Calibration	
	Summary	
	7 Problems	
Chapt	er 3 Measurement Uncertainty	39
-	Introduction	
	2 Sources of Systematic Error	
	3.2.1 System Disturbance due to Measurement	
	3.2.2 Errors due to Environmental Inputs	
	3.2.3 Wear in Instrument Components	
	3.2.4 Connecting Leads	
3.3	Reduction of Systematic Errors	
	3.3.1 Careful Instrument Design	
	3.3.2 Calibration	
	3.3.3 Method of Opposing Inputs	49
	3.3.4 High-Gain Feedback	
	3.3.5 Signal Filtering	51
	3.3.6 Manual Correction of Output Reading	51
	3.3.7 Intelligent Instruments	
3.4	4 Quantification of Systematic Errors	52
	3.4.1 Quantification of Individual Systematic Error Components	53
	3.4.2 Calculation of Overall Systematic Error	
	5 Sources and Treatment of Random Errors	
3.6	Statistical Analysis of Measurements Subject to Random Errors	56
	3.6.1 Mean and Median Values	
	3.6.2 Standard Deviation and Variance	
	3.6.3 Graphical Data Analysis Techniques—Frequency Distributions	
	3.6.4 Gaussian (Normal) Distribution	
	3.6.5 Standard Gaussian Tables (z Distribution)	
	3.6.6 Standard Error of the Mean	
	3.6.7 Estimation of Random Error in a Single Measurement	
	3.6.8 Distribution of Manufacturing Tolerances	70
	3.6.9 Chi-Squared (χ^2) Distribution	71
	3.6.10 Goodness of Fit to a Gaussian Distribution	
	3.6.11 Rogue Data Points (Data Outliers)	
	3.6.12 Student t Distribution	
3.7	Aggregation of Measurement System Errors	
	3.7.1 Combined Effect of Systematic and Random Errors	88
	3.7.2 Aggregation of Errors from Separate Measurement	
	System Components	
	3.7.3 Total Error When Combining Multiple Measurements	92

3.8 Summary	
3.9 Problems	94
Chapter 4 Calibration of Measuring Sensors and Instruments	103
4.1 Introduction	
4.2 Principles of Calibration	
4.3 Control of Calibration Environment	
4.4 Calibration Chain and Traceability	
4.5 Calibration Records	
4.6 Summary	
4.7 Problems	
Chapter 5 Data Acquisition with LabVIEW	115
5.1 Introduction	
5.2 Computer-Based Data Acquisition	
5.2.1 Acquisition of Data	
5.2.1 Acquisition of Data	117
5.3.1 Virtual Instruments	
5.4 Introduction to Graphical Programming in LabVIEW	
5.4.1 Elements of the Tools Palette	120
5.5 Logic Operations in LabVIEW	
5.6 Loops in LabVIEW	
5.7 Case Structure in LabVIEW	
5.8 Data Acquisition Using LabVIEW	
5.9 LabVIEW Function Generation	
5.10 Summary	
5.11 Problems	
5.12 Appendix: Software Tools for Laboratory Data Acquisition	132
5.12.1 Measurement Foundry	
5.12.2 DasyLab	133
5.12.3 iNET-iWPLUS	133
5.12.4 WinWedge	133
Chapter 6 Signal Processing with LabVIEW	135
6.1 Introduction	
6.2 Analogue Filters	
6.2.1 Passive Filters	
6.2.2 Active Filters Using Op-amps	
6.2.3 Implementation on a Breadboard	
6.2.4 Building the Circuit	
6.2.5 Electronic Components	
6.2.6 Op-amps in Analogue Signal Processing	
6.3 Digital Filters	
6.3.1 Input Averaging Filter	145

	6.3.2 Filter with Memory	146
	6.3.3 Example	146
	6.3.4 LabVIEW Implementation	148
	6.3.5 Higher Order Digital Filters	
	Conclusions	
6.5	Problems	152
	Appendix	
	6.6.1 Simple Filter Solution	
	6.6.2 Matlab Solution to the Butterworth Filter Design	
Chapter	7 Electrical Indicating and Test Instruments	161
-	Introduction	
	Digital Meters	
	7.2.1 Voltage-to-Time Conversion Digital Voltmeter	
	7.2.2 Potentiometric Digital Voltmeter	
	7.2.3 Dual-Slope Integration Digital Voltmeter	
	7.2.4 Voltage-to-Frequency Conversion Digital Voltmeter	
	7.2.5 Digital Multimeter	164
	Analogue Meters	
	7.3.1 Moving Coil Meter	
	7.3.2 Moving Iron Meter	167
	7.3.3 Clamp-on Meters	168
	7.3.4 Analogue Multimeter	169
	7.3.5 Measuring High-Frequency Signals with Analogue Meters	
	7.3.6 Calculation of Meter Outputs for Nonstandard Waveforms	
	Oscilloscopes	
	7.4.1 Analogue Oscilloscope (Cathode Ray Oscilloscope)	
	7.4.2 Digital Storage Oscilloscopes	
	7.4.3 Digital Phosphor Oscilloscope	
	7.4.4 Digital Sampling Oscilloscope	
	7.4.5 Personal Computer-Based Oscilloscope	
	Summary	
7.6	Problems	181
Chapter	8 Display, Recording, and Presentation of Measurement Data	183
8.1	Introduction	183
8.2	Display of Measurement Signals	184
	8.2.1 Electronic Output Displays	
	8.2.2 Computer Monitor Displays	
8.3	Recording of Measurement Data	185
	8.3.1 Chart Recorders	185
	8.3.2 Ink-Jet and Laser Printers	190
	8.3.3 Other Recording Instruments	190
	8.3.4. Digital Data Recorders	190

8.4	Presentation of Data	191
	8.4.1 Tabular Data Presentation	191
	8.4.2 Graphical Presentation of Data	192
8.5	Summary	202
8.6	Problems	203
Chapter	· 9 Variable Conversion Elements	207
9.1	Introduction	208
9.2	Bridge Circuits	208
	9.2.1 Null-Type d.c. Bridge (Wheatstone Bridge)	208
	9.2.2 Deflection-Type d.c. Bridge	
	9.2.3 Error Analysis	218
	9.2.4 a.c. Bridges	
	9.2.5 Commercial Bridges	226
9.3	Resistance Measurement	226
	9.3.1 d.c. Bridge Circuit	226
	9.3.2 Voltmeter–Ammeter Method	
	9.3.3 Resistance–Substitution Method	227
	9.3.4 Use of Digital Voltmeter to Measure Resistance	228
	9.3.5 Ohmmeter	
9.4	Inductance Measurement	229
9.5	Capacitance Measurement	229
9.6	Current Measurement	230
9.7	Frequency Measurement	232
	9.7.1 Digital Counter/Timer	
	9.7.2 Phase-Locked Loop	233
	9.7.3 Oscilloscope	234
	9.7.4 Wien Bridge	235
9.8	Phase Measurement	
	9.8.1 Electronic Counter/Timer	236
	9.8.2 X–Y Plotter	237
	9.8.3 Oscilloscope	237
	9.8.4 Phase-Sensitive Detector	238
9.9	Summary	238
9.10	Problems	239
Chapter	· 10 Measurement Signal Transmission	245
	Introduction	
	Electrical Transmission	
10.2	10.2.1 Transmission as Varying Voltages	
	10.2.2 Current Loop Transmission	
	10.2.3 Transmission Using an a.c. Carrier	
10.3	Pneumatic Transmission	
	Fiber-Optic Transmission	
20	10.4.1 Principles of Fiber Optics.	

	10.4.2 Transmission Characteristics	254
	10.4.3 Multiplexing Schemes	256
10.5	Optical Wireless Telemetry	
	Radiotelemetry (Radio Wireless Transmission)	
	Digital Transmission Protocols	
	Summary	
	Problems	
Chapter	11 Intelligent Devices	265
11.1	Introduction	265
11.2	Principles of Digital Computation	266
	11.2.1 Elements of a Computer	
	11.2.2 Computer Operation	
	11.2.3 Computer Input—Output Interface	
	11.2.4 Practical Considerations in Adding Computers	
	to Measurement Systems	273
11.3	Intelligent Devices	
	11.3.1 Intelligent Instruments	
	11.3.2 Smart Sensors	
	11.3.3 Smart Transmitters	278
11.4	Communication with Intelligent Devices	280
	11.4.1 Input–Output Interface	
	11.4.2 Parallel Data Bus	
	11.4.3 Local Area Networks	
	11.4.4 Digital Fieldbuses	
11.5	Summary	
	Problems	
Chapter	12 Measurement Reliability and Safety Systems	291
	Introduction	
12.2	Reliability	293
	12.2.1 Principles of Reliability	
	12.2.2 Laws of Reliability in Complex Systems	
	12.2.3 Improving Measurement System Reliability	
	12.2.4 Software Reliability	
12.3	Safety Systems	
	12.3.1 Introduction to Safety Systems	
	12.3.2 Design of a Safety System	
12.4	Summary	
	Problems	
Chapter	13 Sensor Technologies	317
-	Introduction	
	Capacitive Sensors	
	Resistive Sensors	

1/1 8	Quartz Thermometers	377
	Fiber-Optic Temperature Sensors	
	Color Indicators	
	Change of State of Materials	
	Intelligent Temperature-Measuring Instruments	
	Choice between Temperature Transducers	
14.14	Calibration of Temperature Transducers	
	14.14.1 Reference Instruments and Special Calibration Equipment	
	14.14.2 Calculating Frequency of Calibration Checks	
1 / 15	14.14.3 Procedures for Calibration	
	Summary	
14.10	Problems	392
Chapter 1	5 Pressure Measurement	<i>397</i>
15.1	Introduction.	
15.2	Diaphragms	
15.3	Capacitive Pressure Sensor	
15.4	Fiber-Optic Pressure Sensors	
15.5	Bellows	
15.6	Bourdon Tube	
15.7	Manometers	
13.7	15.7.1 U-Tube Manometer	
	15.7.2 Well-Type Manometer (Cistern Manometer)	
	15.7.3 Inclined Manometer (Draft Gauge)	
15.8	Resonant Wire Devices	
	Electronic Pressure Gauges	
13.10	Special Measurement Devices for Low Pressures	
	15.10.1 Thermocouple Gauge	
	15.10.2 Thermistor Gauge	
	15.10.3 Pirani Gauge	
	15.10.4 McLeod Gauge	
15 11	15.10.5 Ionization Gauge	
	High-Pressure Measurement (Greater than 7000 bar)	
	Intelligent Pressure Transducers	
	Differential Pressure-Measuring Devices	
	Selection of Pressure Sensors	
15.15	Calibration of Pressure Sensors	
	15.15.1 Reference Calibration Instruments	
	15.15.2 Calculating Frequency of Calibration Checks	
	15.15.3 Procedures for Calibration	
	Summary	
15.17	Problems	422
Chapter 1	6 Flow Measurement	125
•		
16.1 16.2	Introduction	
10.2	Mass Tow Nate	

		16.2.1 Conveyor-Based Methods	427
		16.2.2 Coriolis Flowmeter	
		16.2.3 Thermal Mass Flow Measurement	429
		16.2.4 Joint Measurement of Volume Flow Rate and	
		Fluid Density	429
	16.3	Volume Flow Rate	
		16.3.1 Differential Pressure (Obstruction-Type) Meters	430
		16.3.2 Variable Area Flowmeters (Rotameters)	435
		16.3.3 Positive Displacement Flowmeters	436
		16.3.4 Turbine Meters	
		16.3.5 Electromagnetic Flowmeters	
		16.3.6 Vortex-Shedding Flowmeters	
		16.3.7 Ultrasonic Flowmeters	442
		16.3.8 Other Types of Flowmeters for Measuring Volume	
		Flow Rate	
		16.3.9 Open Channel Flowmeters	
		Intelligent Flowmeters	
		Choice between Flowmeters for Particular Applications	
	16.6	Calibration of Flowmeters	451
		16.6.1 Calibration Equipment and Procedures for	
		Mass Flow-Measuring Instruments	452
		16.6.2 Calibration Equipment and Procedures for	
		Instruments Measuring Volume Flow Rate of Liquids	452
		16.6.3 Calibration Equipment and Procedures for	
		Instruments Measuring Volume Flow Rate of Gases	
	167	16.6.4 Reference Standards	
		Summary	
	16.8	Problems	459
Ch	apter	17 Level Measurement	461
	17.1	Introduction	461
	17.2		
	17.3	•	
	17.4		
	17.5		
	17.6		
	17.7	Radar (Microwave) Sensors	467
	17.8	Nucleonic (or Radiometric) Sensors	468
	17.9	Other Techniques	469
		17.9.1 Vibrating Level Sensor	469
		17.9.2 Laser Methods	470
		O Intelligent Level-Measuring Instruments	
	17.11	1 Choice between Different Level Sensors	470
		2 Calibration of Level Sensors	
		3 Summary	
	171	4 Problems	475

Chapter	18 Mass, Force, and Torque Measurement	<i>477</i>
•	Introduction	
	Mass (Weight) Measurement	
	18.2.1 Electronic Load Cell (Electronic Balance)	479
	18.2.2 Pneumatic and Hydraulic Load Cells	
	18.2.3 Intelligent Load Cells	
	18.2.4 Mass Balance (Weighing) Instruments	483
	18.2.5 Spring Balance	486
18.3	Force Measurement	487
	18.3.1 Use of Accelerometers	487
	18.3.2 Vibrating Wire Sensor	
	18.3.3 Use of Load Cells	
18.4	Torque Measurement	488
	18.4.1 Measurement of Induced Strain	
	18.4.2 Optical Torque Measurement	
	18.4.3 Reaction Forces in Shaft Bearings	
	18.4.4 Prony Brake	
18.5	Calibration of Mass, Force, and Torque Measuring Sensors	
	18.5.1 Mass Calibration	
	18.5.2 Force Sensor Calibration	
	18.5.3 Calibration of Torque Measuring Systems	
	Summary	
18.7	Problems	496
Chapter	19 Translational Motion, Vibration, and Shock Measurement	107
•	Introduction	
19.2	Displacement	
	19.2.2 Linear Variable Differential Transformer (LVDT)	
	19.2.3 Variable Capacitance Transducers	
	19.2.4 Variable Inductance Transducers	
	19.2.5 Strain Gauges	
	19.2.6 Piezoelectric Transducers	
	19.2.7 Nozzle Flapper	
	19.2.8 Other Methods of Measuring Small/Medium-Sized Displacements	
	19.2.9 Measurement of Large Displacements (Range Sensors)	
	19.2.10 Proximity Sensors	
	19.2.11 Choosing Translational Measurement Transducers	
	19.2.12 Calibration of Translational Displacement	
	Measurement Transducers	517
19 3	Velocity	
17.3	19.3.1 Differentiation of Displacement Measurements	
	19.3.2 Integration of Output of an Accelerometer	
	19.3.3 Conversion to Rotational Velocity	
	19.3.4 Calibration of Velocity Measurement Systems	

19.4	Acceleration	519
	19.4.1 Selection of Accelerometers	521
	19.4.2 Calibration of Accelerometers	
19.5	Vibration	
-,	19.5.1 Nature of Vibration	
	19.5.2 Vibration Measurement	
	19.5.3 Calibration of Vibration Sensors	
19.6	Shock	
17.0	19.6.1 Calibration of Shock Sensors	
19.7	Summary	
	Problems	
	20 Rotational Motion Transducers	
	Introduction	
	Rotational Displacement	
20.2	20.2.1 Circular and Helical Potentiometers	
	20.2.2 Rotational Differential Transformer	
	20.2.3 Incremental Shaft Encoders	
	20.2.4 Coded Disc Shaft Encoders	
	20.2.5 The Resolver	
	20.2.6 The Synchro	
	20.2.7 The Induction Potentiometer	
	20.2.8 The Rotary Inductosyn	
	20.2.9 Gyroscopes	
	20.2.10 Choice between Rotational Displacement Transducers	
	20.2.11 Calibration of Rotational Displacement Transducers	
20.3	Rotational Velocity	
20.3	20.3.1 Digital Tachometers	
	20.3.2 Stroboscopic Methods	
	20.3.3 Analogue Tachometers	
	20.3.4 The Rate Gyroscope	
	20.3.5 Fiber-Optic Gyroscope	
	20.3.6 Differentiation of Angular Displacement Measurements	
	20.3.7 Integration of Output from an Accelerometer	
	20.3.8 Choice between Rotational Velocity Transducers	
	20.3.9 Calibration of Rotational Velocity Transducers	
20.4	Rotational Acceleration	
20	20.4.1 Calibration of Rotational Accelerometers	
20.5	Summary	
	Problems	
Appendi	x 1 Imperial-Metric-SI Coversion Tables	561
	x 2 Thévenin's Theorem	
	x 3 Thermocouple Tables	
, тррени.	יייייייייייייייייייייייייייייייייייייי	
Index		581