Measurement and Instrumentation

Theory and Application

characteristics instrument types measurement systems, sensor technologies reliability principles Green Constitution precision bins sensitivity resolution measurement uncertainty calibration environment calloration environment prosourors measuring sensors accelerometers working standard variable conversion elements signal transmission labview oscilloscopes digital computation intelligent devices reliability input-output interface self-calibration Will agonic & intelligent sens Sand cell mars halance hadronien State Land Barrage Industring In the Industry Capacitive sensor The Assessment of Becomberation with

Alan S. Morris Reza Langari



Contents

| Acknou | rledgement | xvii |
|---------|---|------|
| Preface | | xix |
| Chapte | r 1 Fundamentals of Measurement Systems | 1 |
| | Introduction | |
| | Measurement Units | |
| 1.3 | Measurement System Design | 3 |
| | 1.3.1 Elements of a Measurement System | |
| | 1.3.2 Choosing Appropriate Measuring Instruments | |
| 1.4 | Measurement System Applications | |
| 1.5 | Summary | 10 |
| 1.6 | Problems | 10 |
| Chapte | r 2 Instrument Types and Performance Characteristics | 11 |
| - | Introduction | |
| | Review of Instrument Types | |
| | 2.2.1 Active and Passive Instruments | |
| | 2.2.2 Null-Type and Deflection-Type Instruments | |
| | 2.2.3 Analogue and Digital Instruments | |
| | 2.2.4 Indicating Instruments and Instruments with a Signal Output | |
| | 2.2.5 Smart and Nonsmart Instruments | |
| 2.3 | Static Characteristics of Instruments | 17 |
| | 2.3.1 Accuracy and Inaccuracy (Measurement Uncertainty) | 17 |
| | 2.3.2 Precision/Repeatability/Reproducibility | 18 |
| | 2.3.3 Tolerance | 20 |
| | 2.3.4 Range or Span | 20 |
| | 2.3.5 Linearity | 20 |
| | 2.3.6 Sensitivity of Measurement | |
| | 2.3.7 Threshold | 22 |
| | 2.3.8 Resolution | 22 |
| | 2.3.9 Sensitivity to Disturbance | |
| | 2.3.10 Hysteresis Effects | |
| | 2.3.11 Dead Space | 26 |

| 2.4 | Dynamic Characteristics of Instruments | 26 |
|-------|--|----|
| | 2.4.1 Zero-Order Instrument | |
| | 2.4.2 First-Order Instrument | 28 |
| | 2.4.3 Second-Order Instrument | 31 |
| 2.5 | Necessity for Calibration | |
| | Summary | |
| | 7 Problems | |
| Chapt | er 3 Measurement Uncertainty | 39 |
| - | Introduction | |
| | 2 Sources of Systematic Error | |
| | 3.2.1 System Disturbance due to Measurement | |
| | 3.2.2 Errors due to Environmental Inputs | |
| | 3.2.3 Wear in Instrument Components | |
| | 3.2.4 Connecting Leads | |
| 3.3 | Reduction of Systematic Errors | |
| | 3.3.1 Careful Instrument Design | |
| | 3.3.2 Calibration | |
| | 3.3.3 Method of Opposing Inputs | 49 |
| | 3.3.4 High-Gain Feedback | |
| | 3.3.5 Signal Filtering | 51 |
| | 3.3.6 Manual Correction of Output Reading | 51 |
| | 3.3.7 Intelligent Instruments | |
| 3.4 | 4 Quantification of Systematic Errors | 52 |
| | 3.4.1 Quantification of Individual Systematic Error Components | 53 |
| | 3.4.2 Calculation of Overall Systematic Error | |
| | 5 Sources and Treatment of Random Errors | |
| 3.6 | Statistical Analysis of Measurements Subject to Random Errors | 56 |
| | 3.6.1 Mean and Median Values | |
| | 3.6.2 Standard Deviation and Variance | |
| | 3.6.3 Graphical Data Analysis Techniques—Frequency Distributions | |
| | 3.6.4 Gaussian (Normal) Distribution | |
| | 3.6.5 Standard Gaussian Tables (z Distribution) | |
| | 3.6.6 Standard Error of the Mean | |
| | 3.6.7 Estimation of Random Error in a Single Measurement | |
| | 3.6.8 Distribution of Manufacturing Tolerances | 70 |
| | 3.6.9 Chi-Squared (χ^2) Distribution | 71 |
| | 3.6.10 Goodness of Fit to a Gaussian Distribution | |
| | 3.6.11 Rogue Data Points (Data Outliers) | |
| | 3.6.12 Student t Distribution | |
| 3.7 | Aggregation of Measurement System Errors | |
| | 3.7.1 Combined Effect of Systematic and Random Errors | 88 |
| | 3.7.2 Aggregation of Errors from Separate Measurement | |
| | System Components | |
| | 3.7.3 Total Error When Combining Multiple Measurements | 92 |

| 3.8 Summary | |
|---|-----|
| 3.9 Problems | 94 |
| Chapter 4 Calibration of Measuring Sensors and Instruments | 103 |
| 4.1 Introduction | |
| 4.2 Principles of Calibration | |
| 4.3 Control of Calibration Environment | |
| 4.4 Calibration Chain and Traceability | |
| 4.5 Calibration Records | |
| 4.6 Summary | 113 |
| 4.7 Problems | 113 |
| Chapter 5 Data Acquisition with LabVIEW | 115 |
| 5.1 Introduction | |
| 5.2 Computer-Based Data Acquisition | 116 |
| 5.2.1 Acquisition of Data | |
| 5.3 National Instruments LabVIEW. | |
| 5.3.1 Virtual Instruments | |
| 5.4 Introduction to Graphical Programming in LabVIEW | |
| 5.4.1 Elements of the Tools Palette | |
| 5.5 Logic Operations in LabVIEW | |
| 5.6 Loops in LabVIEW | |
| 5.7 Case Structure in LabVIEW | |
| 5.8 Data Acquisition Using LabVIEW | 125 |
| 5.9 LabVIEW Function Generation | |
| 5.10 Summary | |
| 5.11 Problems | |
| 5.12 Appendix: Software Tools for Laboratory Data Acquisition | |
| 5.12.1 Measurement Foundry | |
| 5.12.2 DasyLab | |
| 5.12.3 iNET-iWPLUS | |
| 5.12.4 WinWedge | 133 |
| Chapter 6 Signal Processing with LabVIEW | 135 |
| 6.1 Introduction | |
| 6.2 Analogue Filters | 136 |
| 6.2.1 Passive Filters | |
| 6.2.2 Active Filters Using Op-amps | 139 |
| 6.2.3 Implementation on a Breadboard | |
| 6.2.4 Building the Circuit | |
| 6.2.5 Electronic Components | |
| 6.2.6 Op-amps in Analogue Signal Processing | |
| 6.3 Digital Filters | 145 |
| 6.3.1 Input Averaging Filter | 145 |

| | 6.3.2 Filter with Memory | 146 |
|---------|--|-----|
| | 6.3.3 Example | 146 |
| | 6.3.4 LabVIEW Implementation | 148 |
| | 6.3.5 Higher Order Digital Filters | |
| | Conclusions | |
| 6.5 | Problems | 152 |
| | Appendix | |
| | 6.6.1 Simple Filter Solution | |
| | 6.6.2 Matlab Solution to the Butterworth Filter Design | |
| Chapter | 7 Electrical Indicating and Test Instruments | 161 |
| - | Introduction | |
| | Digital Meters | |
| | 7.2.1 Voltage-to-Time Conversion Digital Voltmeter | |
| | 7.2.2 Potentiometric Digital Voltmeter | |
| | 7.2.3 Dual-Slope Integration Digital Voltmeter | |
| | 7.2.4 Voltage-to-Frequency Conversion Digital Voltmeter | |
| | 7.2.5 Digital Multimeter | 164 |
| | Analogue Meters | |
| | 7.3.1 Moving Coil Meter | |
| | 7.3.2 Moving Iron Meter | 167 |
| | 7.3.3 Clamp-on Meters | 168 |
| | 7.3.4 Analogue Multimeter | 169 |
| | 7.3.5 Measuring High-Frequency Signals with Analogue Meters | |
| | 7.3.6 Calculation of Meter Outputs for Nonstandard Waveforms | |
| | Oscilloscopes | |
| | 7.4.1 Analogue Oscilloscope (Cathode Ray Oscilloscope) | |
| | 7.4.2 Digital Storage Oscilloscopes | |
| | 7.4.3 Digital Phosphor Oscilloscope | |
| | 7.4.4 Digital Sampling Oscilloscope | |
| | 7.4.5 Personal Computer-Based Oscilloscope | |
| | Summary | |
| 7.6 | Problems | 181 |
| Chapter | 8 Display, Recording, and Presentation of Measurement Data | 183 |
| 8.1 | Introduction | 183 |
| 8.2 | Display of Measurement Signals | 184 |
| | 8.2.1 Electronic Output Displays | |
| | 8.2.2 Computer Monitor Displays | |
| 8.3 | Recording of Measurement Data | 185 |
| | 8.3.1 Chart Recorders | 185 |
| | 8.3.2 Ink-Jet and Laser Printers | 190 |
| | 8.3.3 Other Recording Instruments | 190 |
| | 8.3.4. Digital Data Recorders | 190 |

| 8.4 | Presentation of Data | 191 |
|---------|--|-----|
| 8 | 8.4.1 Tabular Data Presentation | 191 |
| 8 | 8.4.2 Graphical Presentation of Data | 192 |
| | Summary | |
| | Problems | |
| Chapter | 9 Variable Conversion Elements | 207 |
| 9.1 | Introduction | 208 |
| 9.2 | Bridge Circuits | 208 |
| | 9.2.1 Null-Type d.c. Bridge (Wheatstone Bridge) | 208 |
| | 9.2.2 Deflection-Type d.c. Bridge | 210 |
| | 9.2.3 Error Analysis | 218 |
| | 9.2.4 a.c. Bridges | 220 |
| | 9.2.5 Commercial Bridges | 226 |
| 9.3 | Resistance Measurement | 226 |
| | 9.3.1 d.c. Bridge Circuit | 226 |
| | 9.3.2 Voltmeter–Ammeter Method | 227 |
| | 9.3.3 Resistance–Substitution Method | 227 |
| | 9.3.4 Use of Digital Voltmeter to Measure Resistance | 228 |
| | 9.3.5 Ohmmeter | |
| 9.4 | Inductance Measurement | 229 |
| 9.5 | Capacitance Measurement | 229 |
| | Current Measurement | |
| 9.7 | Frequency Measurement | 232 |
| | 9.7.1 Digital Counter/Timer | |
| | 9.7.2 Phase-Locked Loop | |
| | 9.7.3 Oscilloscope | |
| | 9.7.4 Wien Bridge | |
| 9.8 | Phase Measurement | |
| | 9.8.1 Electronic Counter/Timer | 236 |
| | 9.8.2 X–Y Plotter | 237 |
| | 9.8.3 Oscilloscope | 237 |
| | 9.8.4 Phase-Sensitive Detector | |
| 9.9 | Summary | 238 |
| 9.10 | Problems | 239 |
| Chapter | 10 Measurement Signal Transmission | 245 |
| - | Introduction | |
| | Electrical Transmission | |
| 10.2 | 10.2.1 Transmission as Varying Voltages | |
| | 10.2.2 Current Loop Transmission | |
| | 10.2.3 Transmission Using an a.c. Carrier | |
| 10.3 | Pneumatic Transmission | |
| | Fiber-Optic Transmission | |
| 10.1 | 10.4.1 Principles of Fiber Optics | |
| | · · · · · · · · · · · · · · · · · · · | |

| | 10.4.2 Transmission Characteristics | 254 |
|---------|---|-----|
| | 10.4.3 Multiplexing Schemes | 256 |
| 10.5 | Optical Wireless Telemetry | |
| | Radiotelemetry (Radio Wireless Transmission) | |
| | Digital Transmission Protocols | |
| | Summary | |
| | Problems | |
| Chapter | 11 Intelligent Devices | 265 |
| 11.1 | Introduction | 265 |
| 11.2 | Principles of Digital Computation | 266 |
| | 11.2.1 Elements of a Computer | |
| | 11.2.2 Computer Operation | |
| | 11.2.3 Computer Input—Output Interface | |
| | 11.2.4 Practical Considerations in Adding Computers | |
| | to Measurement Systems | 273 |
| 11.3 | Intelligent Devices | |
| | 11.3.1 Intelligent Instruments | |
| | 11.3.2 Smart Sensors | |
| | 11.3.3 Smart Transmitters | 278 |
| 11.4 | Communication with Intelligent Devices | 280 |
| | 11.4.1 Input–Output Interface | |
| | 11.4.2 Parallel Data Bus | |
| | 11.4.3 Local Area Networks | |
| | 11.4.4 Digital Fieldbuses | |
| 11.5 | Summary | |
| | Problems | |
| Chapter | 12 Measurement Reliability and Safety Systems | 291 |
| | Introduction | |
| 12.2 | Reliability | 293 |
| | 12.2.1 Principles of Reliability | |
| | 12.2.2 Laws of Reliability in Complex Systems | |
| | 12.2.3 Improving Measurement System Reliability | |
| | 12.2.4 Software Reliability | |
| 12.3 | Safety Systems | |
| | 12.3.1 Introduction to Safety Systems | |
| | 12.3.2 Design of a Safety System | |
| 12.4 | Summary | |
| | Problems | |
| Chapter | 13 Sensor Technologies | 317 |
| - | Introduction | |
| | Capacitive Sensors | |
| | Resistive Sensors | |

| 10.4 | 3.6 · · · · · · · · · · · · · · · · · · · | 210 |
|----------------------|--|--|
| | Magnetic Sensors | |
| | Hall-Effect Sensors | |
| | Piezoelectric Transducers | |
| | Strain Gauges | |
| | Piezoresistive Sensors | |
| 13.9 | Optical Sensors | |
| | 13.9.1 Optical Sensors (Air Path) | |
| 40.40 | 13.9.2 Optical Sensors (Fiber Optic) | |
| 13.10 | Ultrasonic Transducers | |
| | 13.10.1 Transmission Speed | |
| | 13.10.2 Directionality of Ultrasound Waves | 334 |
| | 13.10.3 Relationship Between Wavelength, Frequency, and | |
| | Directionality of Ultrasound Waves | |
| | 13.10.4 Attenuation of Ultrasound Waves | |
| | 13.10.5 Ultrasound as a Range Sensor | |
| | 13.10.6 Effect of Noise in Ultrasonic Measurement Systems | |
| | 13.10.7 Exploiting Doppler Shift in Ultrasound Transmission | |
| | Nuclear Sensors | |
| | Microsensors | |
| 13.13 | Summary | 342 |
| 13.14 | Problems | 345 |
| Chapter 1 | 14 Temperature Measurement | 3/17 |
| | Introduction | |
| | | |
| 1/1/2 | I harmoalactric Httact Vancore (I harmocounted) | |
| 14.2 | Thermoelectric Effect Sensors (Thermocouples) | |
| 14.2 | 14.2.1 Thermocouple Tables | 354 |
| 14.2 | 14.2.1 Thermocouple Tables | 354 354 |
| 14.2 | 14.2.1 Thermocouple Tables | 354 354 357 |
| 14.2 | 14.2.1 Thermocouple Tables | 354 354 357 |
| 14.2 | 14.2.1 Thermocouple Tables | 354 354 357 359 |
| 14.2 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature. 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile. | 354 357 359 360 |
| 14.2 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer | 354 357 359 360 361 |
| | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple | 354 357 360 361 361 |
| | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices | 354 357 360 361 361 362 |
| | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature | 354 357 359 360 361 361 362 363 |
| 14.3 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors | 354 357 369 361 361 362 363 363 |
| 14.3 14.4 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors Semiconductor Devices | 354 354 357 360 361 361 363 363 364 |
| 14.3 14.4 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors Semiconductor Devices Radiation Thermometers | 354 354 357 360 361 361 362 363 364 366 |
| 14.3 14.4 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature | 354 354 357 360 361 361 362 363 366 366 366 |
| 14.3 14.4 14.5 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature | 354 354 357 360 361 361 362 363 364 366 366 366 |
| 14.3 14.4 14.5 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors Semiconductor Devices Radiation Thermometers 14.5.1 Optical Pyrometer 14.5.2 Radiation Pyrometers Thermography (Thermal Imaging) | 354 354 357 360 361 361 363 364 366 366 366 366 369 |
| 14.3 14.4 14.5 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors Semiconductor Devices Radiation Thermometers 14.5.1 Optical Pyrometer 14.5.2 Radiation Pyrometers Thermography (Thermal Imaging) Thermal Expansion Methods | 354 354 357 360 361 361 362 363 364 366 366 366 369 373 |
| 14.3 14.4 14.5 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature | 354 354 357 360 361 361 362 363 366 366 366 366 367 375 |
| 14.3 14.4 14.5 | 14.2.1 Thermocouple Tables 14.2.2 Nonzero Reference Junction Temperature 14.2.3 Thermocouple Types 14.2.4 Thermocouple Protection 14.2.5 Thermocouple Manufacture 14.2.6 Thermopile 14.2.7 Digital Thermometer 14.2.8 Continuous Thermocouple Varying Resistance Devices 14.3.1 Resistance Thermometers (Resistance Temperature Devices) 14.3.2 Thermistors Semiconductor Devices Radiation Thermometers 14.5.1 Optical Pyrometer 14.5.2 Radiation Pyrometers Thermography (Thermal Imaging) Thermal Expansion Methods | 354354357369361361362366366366367375375 |

| 14.8 | Quartz Thermometers | 377 |
|---------|---|-----|
| | Fiber-Optic Temperature Sensors | |
| | Color Indicators | |
| | Change of State of Materials | |
| | Intelligent Temperature-Measuring Instruments | |
| | Choice between Temperature Transducers | |
| | Calibration of Temperature Transducers | |
| | 14.14.1 Reference Instruments and Special Calibration Equipment | |
| | 14.14.2 Calculating Frequency of Calibration Checks | |
| | 14.14.3 Procedures for Calibration | 387 |
| 14.15 | Summary | 389 |
| | Problems | |
| Chapter | 15 Pressure Measurement | 397 |
| 15.1 | Introduction | 398 |
| 15.2 | Diaphragms | 399 |
| 15.3 | Capacitive Pressure Sensor | |
| 15.4 | Fiber-Optic Pressure Sensors | |
| 15.5 | Bellows | |
| 15.6 | Bourdon Tube | |
| 15.7 | Manometers | |
| | 15.7.1 U-Tube Manometer | 405 |
| | 15.7.2 Well-Type Manometer (Cistern Manometer) | |
| | 15.7.3 Inclined Manometer (Draft Gauge) | |
| 15.8 | Resonant Wire Devices | |
| 15.9 | Electronic Pressure Gauges | 408 |
| 15.10 | Special Measurement Devices for Low Pressures | |
| | 15.10.1 Thermocouple Gauge | 409 |
| | 15.10.2 Thermistor Gauge | 410 |
| | 15.10.3 Pirani Gauge | 410 |
| | 15.10.4 McLeod Gauge | 410 |
| | 15.10.5 Ionization Gauge | 412 |
| | High-Pressure Measurement (Greater than 7000 bar) | |
| | Intelligent Pressure Transducers | |
| 15.13 | Differential Pressure-Measuring Devices | 413 |
| | Selection of Pressure Sensors | |
| 15.15 | Calibration of Pressure Sensors | 415 |
| | 15.15.1 Reference Calibration Instruments | 416 |
| | 15.15.2 Calculating Frequency of Calibration Checks | 419 |
| | 15.15.3 Procedures for Calibration | |
| | Summary | |
| 15.17 | Problems | 422 |
| Chapter | 16 Flow Measurement | 425 |
| 16.1 | Introduction | |
| | Mass Flow Rate | |

| | | 16.2.1 Conveyor-Based Methods | |
|-----|----------------|--|-----|
| | | 16.2.2 Coriolis Flowmeter | |
| | | 16.2.3 Thermal Mass Flow Measurement | 429 |
| | | 16.2.4 Joint Measurement of Volume Flow Rate and | |
| | | Fluid Density | |
| | 16.3 | Volume Flow Rate | |
| | | 16.3.1 Differential Pressure (Obstruction-Type) Meters | |
| | | 16.3.2 Variable Area Flowmeters (Rotameters) | |
| | | 16.3.3 Positive Displacement Flowmeters | |
| | | 16.3.4 Turbine Meters | |
| | | 16.3.5 Electromagnetic Flowmeters | |
| | | 16.3.6 Vortex-Shedding Flowmeters | |
| | | 16.3.7 Ultrasonic Flowmeters | 442 |
| | | 16.3.8 Other Types of Flowmeters for Measuring Volume | |
| | | Flow Rate | |
| | | 16.3.9 Open Channel Flowmeters | |
| | | Intelligent Flowmeters | |
| | | Choice between Flowmeters for Particular Applications | |
| | 16.6 | Calibration of Flowmeters | 451 |
| | | 16.6.1 Calibration Equipment and Procedures for | |
| | | Mass Flow-Measuring Instruments | 452 |
| | | 16.6.2 Calibration Equipment and Procedures for | |
| | | Instruments Measuring Volume Flow Rate of Liquids | 452 |
| | | 16.6.3 Calibration Equipment and Procedures for | |
| | | Instruments Measuring Volume Flow Rate of Gases | |
| | | 16.6.4 Reference Standards | |
| | | Summary | |
| | 16.8 | Problems | 459 |
| Ch | ahter | 17 Level Measurement | 461 |
| C// | 17.1 | Introduction | |
| | 17.1 | Dipsticks | |
| | 17.2 | Float Systems | |
| | 17.3 | | |
| | 17.4 | Pressure-Measuring Devices (Hydrostatic Systems) | |
| | 17.5 | Ultrasonic Level Gauge | |
| | 17.0 | Radar (Microwave) Sensors | |
| | 17.7 | · / | |
| | | Nucleonic (or Radiometric) Sensors | |
| | 17.9 | Other Techniques | |
| | | 17.9.1 Vibrating Level Sensor | |
| | 17 10 | 17.9.2 Laser Methods | |
| | | Intelligent Level-Measuring Instruments | |
| | 7/11 | | 170 |
| | | Choice between Different Level Sensors | |
| | 17.12 | Calibration of Level Sensors | 472 |
| | 17.12 17.13 | | 472 |

| Chapter | 18 Mass, Force, and Torque Measurement | <i>477</i> |
|---------|--|------------|
| • | Introduction | |
| | Mass (Weight) Measurement | |
| | 18.2.1 Electronic Load Cell (Electronic Balance) | 479 |
| | 18.2.2 Pneumatic and Hydraulic Load Cells | |
| | 18.2.3 Intelligent Load Cells | |
| | 18.2.4 Mass Balance (Weighing) Instruments | 483 |
| | 18.2.5 Spring Balance | 486 |
| 18.3 | Force Measurement | 487 |
| | 18.3.1 Use of Accelerometers | 487 |
| | 18.3.2 Vibrating Wire Sensor | |
| | 18.3.3 Use of Load Cells | |
| 18.4 | Torque Measurement | 488 |
| | 18.4.1 Measurement of Induced Strain | |
| | 18.4.2 Optical Torque Measurement | |
| | 18.4.3 Reaction Forces in Shaft Bearings | |
| | 18.4.4 Prony Brake | |
| 18.5 | Calibration of Mass, Force, and Torque Measuring Sensors | |
| | 18.5.1 Mass Calibration | |
| | 18.5.2 Force Sensor Calibration | |
| | 18.5.3 Calibration of Torque Measuring Systems | |
| | Summary | |
| 18.7 | Problems | 496 |
| Chapter | 19 Translational Motion, Vibration, and Shock Measurement | 107 |
| • | Introduction | |
| | | |
| 19.2 | Displacement | |
| | 19.2.2 Linear Variable Differential Transformer (LVDT) | |
| | 19.2.3 Variable Capacitance Transducers | |
| | 19.2.4 Variable Inductance Transducers | |
| | 19.2.5 Strain Gauges | |
| | 19.2.6 Piezoelectric Transducers | |
| | 19.2.7 Nozzle Flapper | |
| | 19.2.8 Other Methods of Measuring Small/Medium-Sized Displacements | |
| | 19.2.9 Measurement of Large Displacements (Range Sensors) | |
| | 19.2.10 Proximity Sensors | |
| | 19.2.11 Choosing Translational Measurement Transducers | |
| | 19.2.12 Calibration of Translational Displacement | |
| | Measurement Transducers | 517 |
| 19 3 | Velocity | |
| 17.3 | 19.3.1 Differentiation of Displacement Measurements | |
| | 19.3.2 Integration of Output of an Accelerometer | |
| | 19.3.3 Conversion to Rotational Velocity | |
| | 19.3.4 Calibration of Velocity Measurement Systems | |
| | | |

| 19.4 | Acceleration | 519 |
|---------|---|-----|
| | 19.4.1 Selection of Accelerometers | 521 |
| | 19.4.2 Calibration of Accelerometers | 521 |
| 19.5 | Vibration | 522 |
| | 19.5.1 Nature of Vibration | 522 |
| | 19.5.2 Vibration Measurement | 523 |
| | 19.5.3 Calibration of Vibration Sensors | 525 |
| 19.6 | Shock | 525 |
| | 19.6.1 Calibration of Shock Sensors | 526 |
| 19.7 | Summary | 526 |
| 19.8 | Problems | 528 |
| Chapter | 20 Rotational Motion Transducers | 529 |
| | Introduction | |
| | Rotational Displacement | |
| 20.2 | 20.2.1 Circular and Helical Potentiometers | |
| | 20.2.2 Rotational Differential Transformer | |
| | 20.2.3 Incremental Shaft Encoders | |
| | 20.2.4 Coded Disc Shaft Encoders | |
| | 20.2.5 The Resolver | |
| | 20.2.6 The Synchro | |
| | 20.2.7 The Induction Potentiometer | |
| | 20.2.8 The Rotary Inductosyn | |
| | 20.2.9 Gyroscopes | |
| | 20.2.10 Choice between Rotational Displacement Transducers | |
| | 20.2.11 Calibration of Rotational Displacement Transducers | |
| 20.3 | Rotational Velocity | |
| | 20.3.1 Digital Tachometers | |
| | 20.3.2 Stroboscopic Methods | |
| | 20.3.3 Analogue Tachometers | |
| | 20.3.4 The Rate Gyroscope | |
| | 20.3.5 Fiber-Optic Gyroscope | |
| | 20.3.6 Differentiation of Angular Displacement Measurements | |
| | 20.3.7 Integration of Output from an Accelerometer | |
| | 20.3.8 Choice between Rotational Velocity Transducers | |
| | 20.3.9 Calibration of Rotational Velocity Transducers | |
| 20.4 | Rotational Acceleration | 558 |
| | 20.4.1 Calibration of Rotational Accelerometers | 559 |
| 20.5 | Summary | 559 |
| 20.6 | Problems | 560 |
| Appendi | x 1 Imperial-Metric-SI Coversion Tables | 561 |
| | x 2 Thévenin's Theorem | |
| | x 3 Thermocouple Tables | |
| 11 | • | |
| Index | | 581 |