



Service order list

Page 1

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
AGE01090	IPF8100	IPF8100	201	BR	Glory Copy Center TCA behind Al reyami bldg.	A203

Service order id	Status	Job type	Prio	Tech	43563	ABU DHABI	Called in by	Phone	Cell Phone
53408.02	13	82	2	E106	Called in by	Mr. Sunil George	02 6445705		
Called in	Time	Planned	Time	Delegated	Time		Stoppage	Service day	
09/12/2010	11.40	02/03/2011	0.00	0.00	18/04/2011	0.00	No	0	

Called in work
AH ERROR CODE / MESSAGE

Description

jo55698, main bord Dimm assy
ordered to ge --- 13/2 richie
jo62890, need flexible cable assy

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
QM3-2005-020006	FLEXIBLE CABLE ASS'Y			ADSH	1.00	344.42	344.42	750.00	750.00
SC-CORP-1000	Service Charge			ADSH	1.00	0.00	0.00	1,000.00	750.00
							344.42		1,500.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
ABD00425	IR5055N	IR5055N	103	CX	Veco Engineering 18/F Siemens Bldg, Electra St.	709

Service order id	Status	Job type	Prio	Tech	45570	ABU DHABI	Called in by	Phone	Cell Phone
56843.01	13	82	2	E125	Called in by	Nema	02 4013800		
Called in	Time	Planned	Time	Delegated	Time		Stoppage	Service day	
06/02/2011	10.25		0.00	0.00	08/02/2011	0.00	No	0	

Called in work
Description
m/c not working

jo 59624

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FC9-3656-000000	ROLLER, REGISTRATION, 2			ADSH	2.00	17.44	34.88	100.00	0.00
							34.88		0.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
FTK30155	IR2530	IR2530	102	CX	Pembinaan SPK SDN BHD Al Falah	1

Service order id	Status	Job type	Prio	Tech	109942	ABU DHABI	Called in by	Phone	Cell Phone
58257.01	13	82	2	144	Called in by	Dona	02 5564479		
Called in	Time	Planned	Time	Delegated	Time		Stoppage	Service day	
27/02/2011	8.30	27/02/2011	0.00	0.00	20/04/2011	0.00	No	0	

Called in work
BC PAPER FEED

Description

jo63151, need paper pick up

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM3-9230-000000	PAPER PICK-UP ASSEMBLY, LAR			ADSH	1.00	224.61	224.61	750.00	0.00
FM3-9372-000000	PAPER PICK-UP ASSEMBLY			ADSH	1.00	1,002.66	1,002.66	2,900.00	0.00
							1,227.27		0.00
				0.00	0.00		0.00	0.00	



Service order list

Page 2

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
FAK05828	IRAC2020i	IRAC2020i	200	CG	Arabian Construction Co LL(Ruweis, ATS Project	A505
Service order id	Status	Job type	Prio	Tech	2113 Called in by	ABU DHABI
59313.01	13	82	2	143	Ejas	Phone
Called in	Time	Planned	Time	Delegated	Time	050 3061080
14/03/2011	8.01		0.00	0.00	23/03/2011	0.00
						Stoppage
						No
						Cell Phone
						0
Called in work						
BC PAPER FEED						
Description						
feeder pp jamming						
jo63668, need hing left & screw step						
Actions						
Action description						
Start date	Time	End date	Time	Technician	Job type	
Item id	Description			Tech	Quantity	Cost price
FC8-6420-000000	HIDGE, LEFT			ADSH	1.00	137.34
FU5-9140-000000	SCREW, STEPPED, M4X10			ADSH	2.00	1.04
						139.42
						0.00
						0.00
						0.00

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MVA06712	IR3045N	IR3045N	103	CX	Abu Dhabi Police GHQ Traffic Complex	1
Service order id	Status	Job type	Prio	Tech	PO Box Called in by	AL AIN
59681.01	13	82	2	154	Abdulaha	Phone
Called in	Time	Planned	Time	Delegated	Time	050 4499194
20/03/2011	13.50		0.00	0.00	28/03/2011	0.00
						Stoppage
						No
						Cell Phone
						0
Called in work						
AH ERROR CODE / MESSAGE						
Description						
E10,E20						
JO63547						
Actions						
Action description						
Start date	Time	End date	Time	Technician	Job type	
Item id	Description			Tech	Quantity	Cost price
FM2-0287-020000	DEVELOPING ASSY			ADSH	1.00	474.86
FM2-0286-010000	HOPPER ASSEMBLY			ADSH	1.00	267.42
9634A002AA	C-EXV 12 TONER BK EUR iR3530,			ADSH	1.00	256.24
						998.52
						0.00
						0.00
						0.00

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
CBD10337	IR7105	IR7105	501	PF	Arabian Construction Co LL(4th F ,Micco Bldg,Najda	A205
Service order id	Status	Job type	Prio	Tech	2113 Called in by	ABU DHABI
59753.01	13	82	2	E106	Cruz	Phone
Called in	Time	Planned	Time	Delegated	Time	050 7912475
21/03/2011	10.17		0.00	0.00	05/04/2011	0.00
						Stoppage
						No
						Cell Phone
						0
Called in work						
AN IMAGE QUALITY						
Description						
jo63732, need parts						
Actions						
Action description						
Start date	Time	End date	Time	Technician	Job type	
Item id	Description			Tech	Quantity	Cost price
FB5-6930-000000	ROLLER, FIXING			ADSH	1.00	533.95
XG9-0421-000000	BEARING, BALL			ADSH	2.00	19.87
						39.74
						100.00
						0.00



Service order list

Page 3

FB6-2374-000000	ROLLER, PRESSURE	ADSH	1.00	289.45	289.45	750.00	0.00
XG9-0447-000000	BEARING, BALL	ADSH	2.00	18.17	36.34	100.00	0.00
FF5-7829-030000	NR#ROLLER, PICK-UP	ADSH	2.00	7.88	15.76	50.00	0.00
FF5-7830-030000	ROLLER, PICK-UP	ADSH	2.00	7.85	15.70	50.00	0.00
FB5-6586-000000	ROLLER, SPONGE	ADSH	2.00	35.95	71.90	150.00	0.00
FF5-9779-000000	ROLLER, FEED	ADSH	2.00	8.88	17.76	100.00	0.00
					1,020.60		0.00
			0.00	0.00	0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr			
DD416564	DR5010C	DR5010C	300	EM	Mr. Biju John	1			
PO Box 51384									
51384 ABU DHABI									
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone		
59885.01	13	82	2	E126	Mr.Biju	050 5902721			
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
22/03/2011	9.00		0.00		0.00	23/03/2011	0.00	No	0
Called in work									
BP WORKSHOP REPAIR									
Description									
jo63827, need rollers									
Actions									
Action description									
Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
MA2-6772-000000	FEED ROLLER			ADSH	1.00	27.20	27.20	150.00	0.00
							27.20		0.00
			0.00		0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr			
AEN11722	IPF710	IPF710	201	BR	Ibrahim Bin Salith Library c/c Umm Al Nar, Bain Al Jesrain	1			
7070 ABU DHABI									
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone		
60061.01	13	82	2	E106	Anwar	055 9500334			
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
24/03/2011	11.44		0.00		0.00	11/04/2011	0.00	No	0
Called in work									
AN IMAGE QUALITY									
Description									
2F13									
jo64170, need main board									
jo66057, need new board-07/04/2011									
jo66063-10/04/2011									
Actions									
Action description									
Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
QM3-3215-000000	MAIN BOARD DIMM ASS'Y			ADSH	1.00	1,319.59	1,319.59	4,525.00	0.00
							1,319.59		0.00
Start date	Time	End date	Time	Work time	Work costs	Travel time	Traveling costs	Trav. dist.	Technician job type
07/04/2011	10.30	07/04/2011	12.20	1.83	96.99	0.68	36.04	25.00	E106 82
				1.83	96.99	0.68	36.04	25.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr	
FTK01096	IR2530	IR2530	102	CX	JGC Corporation Habshan	1	
28543 ABU DHABI							
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
60177.01	13	82	2	143	Mohd Ali	050 6173955	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
27/03/2011	13.32		0.00		0.00	No	0



Service order list

Page 4

Called in work

AH ERROR CODE / MESSAGE

Description

E60

jo63691, need fixing film assy

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM3-9382-000000	FIXING FILM ASSEMBLY			ADSH	1.00	456.42	456.42	750.00	750.00
							456.42		750.00
			0.00		0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr	
MNZ26300	IRC2880i	IRC2880i	200	CG	Al Habtoor Engineering Airport Road, Opp pepsi Cola 320 320 ABU DHABI		
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
60180.01	13	82	2	E106	Nasser	02 4492387	
Called in	Time	Planned	Time	Booked	Time	Delegated	Time
24/03/2011	13.30		0.00		0.00	20/04/2011	0.00
						Stoppage	Service day
						No	0

Called in work

AN IMAGE QUALITY

Description

jo 064156

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
0456B002BA 00DU	IRC3380/2880		C-EXV2	ADSH	1.00	555.35	555.35	2,000.00	2,000.00
0457B002BA 00DU	IRC3380/2880		C-EXV2	ADSH	1.00	1,038.82	1,038.82	2,900.00	2,900.00
0458B002BA 00DU (M)	IRC2880/3380		C-EX1	ADSH	1.00	1,039.30	1,039.30	2,900.00	2,900.00
0459B002BA 00DU	IRC3380/2880		C-EXV2	ADSH	1.00	1,035.84	1,035.84	2,900.00	2,900.00
FB6-3405-000000	ROLLER, PAPER PICK-UP			ADSH	2.00	8.51	17.02	50.00	0.00
FC6-7083-000000	ROLLER, FEED/SEPARATION			ADSH	2.00	8.19	16.38	100.00	0.00
FC6-6661-000000	ROLLER, SEPARATION			ADSH	2.00	14.35	28.70	100.00	0.00
							3,731.41		10,700.00
			0.00		0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr		
DJR00960	IR5055N	IR5055N	103	CX	Ministry of Higher Education Customer Service, Najda	710		
					45253	ABU DHABI		
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone	
60404.01	13	82	2	CE122	Samba	050 2631906		
Called in	Time	Planned		Delegated	Time	Stoppage	Service day	
29/03/2011	14.10			0.00	18/04/2011	0.00	No	0

Called in work

BQ PREVENTIVE MAINTENANCE

Description

jo63991, need bottle drive

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM2-3024-000000	BOTTLE DRIVE ASSEMBLY			ADSH	1.00	205.96	205.96	600.00	540.00
							205.96		540.00
			0.00		0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr	
JPF02463	IRC3220N	IRC3220N	200	CG	Waha Capital / Oasis Leasir Buteen, Afeel bldg 4/F	A102	
					28922	ABU DHABI	
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone



Service order list

Page 5

60493.01 13 82 2 E116 Jezil 050 8116201
Called in Time Planned Time Booked Time Delegated Time Stoppage Service day
30/03/2011 16.17 07/04/2011 15.00 0.00 03/04/2011 0.00 No 0

Called in work

BC PAPER FEED

Description

contract is on process

jo64075, need rollers. belt & sep pad

jo64287, replaced standby DADF, waiting for parts-07/04/2011

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FB6-4978-010000	ROLLER, SEPARATION			ADSH	1.00	33.43	33.43	150.00	0.00
FB4-6934-000000	BELT, FEEDER		PU (F)	ADSH	1.00	113.25	113.25	400.00	0.00
FF5-9160-030000	PAD, SEPARATION		PU (R)	ADSH	1.00	15.03	15.03	100.00	0.00
FB6-4977-010000	ROLLER, PAPER PICK-UP			ADSH	1.00	20.61	20.61	100.00	0.00
							182.32		0.00
							0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
DHM02307	IR3245N	IR3245N	103	CX	Cloisall Company L.L.C Bur Dubai	1001

Service order id	Status	Job type	Prio	Tech	PO Box 336 DUBAI	Phone	Cell Phone
Called in	Time	Planned	Time	Delegated	Called in by	Stoppage	Service day
60736.01	13	82	2	E123	Lijo	04 3258484	0
28/03/2011	10.45	20/04/2011	0.00	0.00		No	0

Called in work

BQ PREVENTIVE MAINTENANCE

Description

JO64734-need fixing assy, drum & rollers (parts issuance

still on hold as per accts--jane 4/4/2011, ok to go as per

accts--jane 20/4/2011)

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM3-7067-000000	FIXING ASSEMBLY			DHLJF	1.00	902.82	902.82	2,500.00	0.00
9630A003BA 000	DRUM IR2230/70/2870/3530/70 /4			DHLJF	1.00	628.87	628.87	1,400.00	0.00
FB6-3405-000000	ROLLER, PAPER PICK-UP			DHLJF	2.00	8.51	17.02	50.00	0.00
FC6-7083-000000	ROLLER, FEED/SEPARATION			DHLJF	2.00	8.19	16.38	100.00	0.00
FC6-6661-000000	ROLLER, SEPARATION			DHLJF	2.00	14.35	28.70	100.00	0.00
							1,593.79		0.00
							0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
GPV10975	IRAC5045I	IRAC5045I	200	CG	Arabian Construction Co LL Corniche, Pearl Project	702

Service order id	Status	Job type	Prio	Tech	2113 ABU DHABI	Phone	Cell Phone
Called in	Time	Planned	Time	Delegated	Called in by	Stoppage	Service day
60966.01	13	82	2	143	Mohammed Shameem	02 63540146	0
07/04/2011	10.08		0.00	0.00		No	0

Called in work

AN IMAGE QUALITY

Description

jo63944, need coupling

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FC8-4338-000000	COUPLING			ADSH	1.00	0.55	0.55	50.00	0.00
							0.55		0.00



Service order list

Page 6

0.00 0.00 0.00 0.00

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
CZC00103	IR8500	IR8500	104	CX	Abu Dhabi Police GHQ Swehan (Training College)	

Service order id	Status	Job type	Prio	Tech	253	AL AIN	Phone	Cell Phone	
61024.01	13	82	2	E111	Called in by	Zia	03 7154210		
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
10/04/2011	8.17	12/04/2011	11.35		0.00	13/04/2011	0.00	No	0

Called in work

BQ PREVENTIVE MAINTENANCE

Description

pls chk & service

jo65904, need web

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FY1-1157-000000	CLEANER SUPPLY ROLL (FIXING			ADSH	1.00	78.42	78.42	400.00	0.00
							78.42		0.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
KFQ15715	IR4570	IR4570	103	CX	Al Ashram Contracting LLC Near Clock Tower, Green Tower 17th flr	116

Service order id	Status	Job type	Prio	Tech	1290	DUBAI	Phone	Cell Phone	
61047.01	13	82	2	E128	Called in by	Clary	04 2294000		
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
10/04/2011	10.02	18/04/2011	12.45		0.00		0.00	No	0

Called in work

AN IMAGE QUALITY

Description

black lines

jo065615, need fixing unit & rollers

Actions

YC REPLACED PART

Action description

JO65647

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FB6-3405-000000	ROLLER, PAPER PICK-UP			DHLJF	2.00	8.51	17.02	50.00	90.00
FC6-7083-000000	ROLLER, FEED/SEPARATION			DHLJF	2.00	8.20	16.40	100.00	180.00
FC6-6661-000000	ROLLER, SEPARATION			DHLJF	2.00	14.34	28.68	100.00	180.00
FB5-4931-000000	ROLLER, FIXING HEATSINK			DHLJF	1.00	16.02	16.02	100.00	90.00
FM2-1812-020000	FIXING FILM UNIT			DHLJF	1.00	352.84	352.84	1,200.00	1,080.00
							430.96		1,620.00
Start date	Time	End date	Time	Work time	Work costs	Travel time	Traveling costs	Trav. dist.	Technician Job type
18/04/2011	12.45	18/04/2011	14.30	1.75	105.00	0.50	30.00	15.00	E128 82
				1.75	105.00	0.50	30.00	15.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
TPP00005	CLC5151	CLC5151	200	CG	Golden Wing Trading Khalifa St.	A108

Service order id	Status	Job type	Prio	Tech	26293	ABU DHABI	Phone	Cell Phone	
61060.01	13	82	2	CE131	Called in by	Binu	02 6275100		
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
07/04/2011	17.30		0.00		0.00	10/04/2011	0.00	No	0

Called in work

AN IMAGE QUALITY



Service order list

Page 7

Description

jo63067, need m drum

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
0256B002AB	00DU IRC4580/4080 CLC5151/4040			ADSH	1.00	945.90	945.90	2,300.00	0.00
							945.90		0.00
							0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
AEN07239	IPF710	IPF710	201	BR	Al Habtoor Specon Khalifa City B, near Airport Road	

Service order id	Status	Job type	Prio	Tech	320	ABU DHABI	Phone	Cell Phone
61162.01	13	82	2	E106	Called in by	Joy	02 5131825	
Called in	Time	Planned	Time	Delegated	Time	Time	Stoppage	Service day
10/04/2011	16.15		0.00	0.00	20/04/2011	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

jo66061, need printhead & main cart, add service charge

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
SC-CORP-500	Service Charge			ADSH	1.00	0.00	0.00	500.00	225.00
1320B008AA	MAINTENANCE C MC-07 IPF70			ADSH	1.00	217.98	217.98	310.00	310.00
2251B001AB	CANON PRINthead PF-03.			ADSH	1.00	1,453.51	1,453.51	1,965.00	1,965.00
							1,671.49		2,500.00
							0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
DJP01764	IR5075N	IR5075N	104	CX	Liwa International School Falaj Hazaa, Near Al ain Traffic Dept.	1

Service order id	Status	Job type	Prio	Tech	81685	AL AIN	Phone	Cell Phone
61221.01	13	82	2	E111	Called in by	Jamal	03 7810444-2;	
Called in	Time	Planned	Time	Delegated	Time	Time	Stoppage	Service day
11/04/2011	17.55		0.00	0.00	20/04/2011	0.00	No	0

Called in work

AH ERROR CODE / MESSAGE

Description

jo65901, need bushing,bearing,gear, roller fixing

partial delivery without gears -john apr 20,2011

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FC7-4276-010000	ROLLER, FIXING			ADSH	1.00	88.26	88.26	300.00	300.00
FM2-9766-000000	THERMISTOR ASS'Y			ADSH	1.00	33.94	33.94	150.00	150.00
FC6-3856-000000	BUSHING	PPS+PAI		ADSH	2.00	14.99	29.98	100.00	200.00
XG9-0563-000000	BEARING BALL, 6809ZZN S1C4 K			ADSH	2.00	20.08	40.16	100.00	200.00
FM2-4161-000000	HOLDER,THERMISTOR			ADSH	1.00	39.76	39.76	150.00	150.00
							232.10		1,000.00
							0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MCW14339	IR2016	IR2016	101	CX	Crown Paper Mill Ajman Fze Gate 4	403

Service order id	Status	Job type	Prio	Tech	4192	AJMAN	Phone	Cell Phone
					Called in by			



Service order list

Page 8

61284.01 13 82 2 134 Durgish 055 7683216
Called in Time Planned Time Booked Time Delegated Time Stoppage Service day
12/04/2011 16.04 19/04/2011 0.00 0.00 0.00 No 0

Called in work

BC PAPER FEED

Description

jo65335, need fixing film

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description	Tech	Quantity						
FM2-3353-000000	FIXING FILM ASSEMBLY	DHLJF	1.00	373.00	373.00	1,100.00	990.00		
FC6-4475-000000	GUIDE, DELIVERY	TRSV	1.00	0.00	0.00	50.00	45.00		
FF6-1621-000000	ROLLER, SEPARATION	DHLJF	2.00	22.19	44.38	100.00	180.00		
FB4-9817-030000	ROLLER, PICK-UP	DHLJF	2.00	3.97	7.94	75.00	135.00		
				425.32			1,350.00		
			0.00	0.00	0.00	0.00			

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
CQC01255	IR5000	IR5000	103	CX	Abu Dhabi Police Sweihan Police Training Institute	1

ABU DHABI

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
Start date	Time	Planned	Time	Delegated	Time	Stoppage	Service day
61311.01	13	82	2	E111	Zia	03 7154210	
Called in	Time		Time	Delegated	Time	No	0
12/04/2011	14.00		0.00	0.00	13/04/2011	0.00	

Called in work

AN IMAGE QUALITY

Description

jo65905, need gear

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description	Tech	Quantity						
FS5-3809-020000	GEAR, 31T/PULLEY, 41T	ADSH	1.00	15.29	15.29	100.00	0.00		
XZ9-0581-000000	CATCH, MAGNET	ADSH	1.00	4.48	4.48	50.00	0.00		
				19.77			0.00		
			0.00	0.00	0.00	0.00			

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MWT09095	IR2022	IR2022	102	CX	Al Nasr Contracting Co LLC Sadiyat Island	

2436 ABU DHABI

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
Start date	Time	Planned	Time	Delegated	Time	Stoppage	Service day
61501.01	13	82	2	E122	Shinju	050 5115608	
Called in	Time		Time	Delegated	Time	No	0
17/04/2011	9.43		0.00	0.00	20/04/2011	0.00	

Called in work

AY NOISE

Description

jo62325, need drum

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description	Tech	Quantity						
2101B002AA 00	DRUM IR2018/2022/25/30	CEXV	ADSH	1.00	541.89	541.89	1,200.00	1,080.00	
					541.89			1,080.00	
			0.00	0.00	0.00	0.00			

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MXM01195	IR2025	IR2025	102	CX	Shar Metal Scrap Co Ltd. Ind Area 2 behind Dynatrade,near J&P	101

128 SHARJAH



Service order list

Page 9

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61551.01	13	82	2	E102	Babu	06 5430007	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
17/04/2011	13.09	20/04/2011	0.00	0.00	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

JO 065810-need drum

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
2101B002AA	00DRUM IR2018/2022/25/30	CEXV	DHLJF	1.00	541.89	541.89	1,200.00	0.00	0.00
						541.89			0.00
			0.00	0.00		0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MCW14330	IR2016	IR2016	101	CX	Bu haleeba opp Lake Palace Hotel- Burj Dubai	124

10874 DUBAI

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61561.01	13	82	2	E124	Mr Iqbal	050 6457152	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
17/04/2011	14.15	19/04/2011	0.00	0.00	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

lines

JO65679-need fixing film

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM2-3353-000000	FIXING FILM ASSEMBLY		DHLJF	1.00	373.00	373.00	1,100.00	0.00	0.00
						373.00			0.00
			0.00	0.00		0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
MCW25513	IR2016	IR2016	101	CX	Bu Haleeba Contracting LLC Site 313, opp of Global Village	1306

10874 DUBAI

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61563.01	13	82	2	E127	Saibaba	050 4733978	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
17/04/2011	15.17	19/04/2011	0.00	0.00	0.00	No	0

Called in work

AH ERROR CODE / MESSAGE

Description

E007

JO65776

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
0385B002BA	00DU IR2016/2020	C-EXV1	DHLJF	1.00	437.84	437.84	1,000.00	0.00	0.00
FM2-3352-000000	FIXING ASSEMBLY		DHLJF	1.00	762.29	762.29	1,900.00	0.00	0.00
FF6-1621-000000	ROLLER, SEPARATION		DHLJF	2.00	22.22	44.44	100.00	0.00	0.00
						1,244.57			0.00
			0.00	0.00		0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
DCF64347	IRC2380i	IRC2380i	200	CG	Premier Composite Techno DIP 2	1401



Service order list

Page 10

282777 DUBAI											
Service order id		Status		Job type		Prio	Tech	Called in by	Phone	Cell Phone	
61564.01		13		82		2	E127	Ajith	04 8868555		
Called in		Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day	
17/04/2011		15.24	20/04/2011	0.00		0.00		0.00	No	0	
Called in work											
AN		IMAGE QUALITY									
Description											
color marks											
JO65774-need fixing film											
Actions											
Action description											
Start date		Time	End date	Time		Technician	Job type				
Item id		Description				Tech	Quantity	Cost price	Total	Price	Total
0456B002BA		00DU	IRC3380/2880	C-EXV2		DHLJF	1.00	555.61	555.61	2,000.00	1,800.00
FM3-1994-000000		FIXING FILM UNIT				DHLJF	1.00	638.68	638.68	1,900.00	1,710.00
								1,194.29		3,510.00	
						0.00	0.00	0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr				
MWM82626	IR2018	IR2018	101	CX	Al Madallah Healthcare Man Dubai Academic City	1305				
							31712 DUBAI			
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone			
61596.01	13	82	2	E124	Mira	055 3214141				
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day			
18/04/2011	10.21	18/04/2011	0.00	0.00	0.00	No	0			
Called in work										
AN IMAGE QUALITY										
Description										
JO65685										
Actions										
Action description										
Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total	
Item id	Description			Tech	Quantity					
FM3-3671-010000	DEVELOPING ASSEMBLY CONST			DHLJF	1.00	360.97	360.97	1,200.00	1,080.00	
							360.97		1,080.00	
			0.00	0.00			0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr				
KRB47723	IR2016	IR2016	101	CX	Gulf Adhesive Label Factory Opposite of Lootah	403				
					Ajman IndiaAJMAN					
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone			
61603.01	13	82	2	134	Sajeevan	06 7436777				
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day	
17/04/2011	14.35	19/04/2011	0.00		0.00		0.00	No	0	
Called in work										
BQ	PREVENTIVE MAINTENANCE									
Description										
JO67002-need drum										
Actions										
Action description										
Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total	
Item id	Description			Tech	Quantity					
0385B002BA	00DU IR2016/2020		C-EXV14	DHLJF	1.00	437.84	437.84	1,000.00	900.00	
							437.84		900.00	
			0.00		0.00		0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr			
AEN02915	IPF710	IPF710	201	BR	Malcolm & Partners JLT JLT, Indigo Icon Tower R204	1506			

18175 DUBAI



Service order list

Page 11

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61662.01	13	82	2	135	George Malcolm	04 4475501	
Called in	Time	Planned	Time	Delegated	Time	Stoppage	Service day
18/04/2011	15.25	19/04/2011	0.00	0.00	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

JO66964-need MC

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
SC-CORP-300	Service Charge			DHLJF	1.00	0.00	0.00	310.00	310.00
1320B008AA	MAINTENANCE C MC-07 IPF70			TR SVC	1.00	217.98	217.98	310.00	0.00
							217.98		310.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
SXK00812	IR7105	IR7105	501	PF	CONNECT 4	703
					Abu Hail, Near Labor Office	

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61663.01	13	82	2	133	Joseph	04 2681610	
Called in	Time	Planned	Time	Delegated	Time	Stoppage	Service day
18/04/2011	16.10	19/04/2011	0.00	0.00	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

JO66913

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FS5-6579-000000	COLLAR			DHLJF	2.00	44.00	88.00	150.00	0.00
FG6-7313-040000	PRIMARY CORONA ASSEMBLY			DHLJF	1.00	354.11	354.11	850.00	0.00
FM2-5857-000000	PRE-TRANSFER CORONA ASSEM			DHLJF	1.00	354.31	354.31	1,000.00	0.00
							796.42		0.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
CNF01252	IR2025i	IR2025i	102	CX	Expat Services GmbH-Duba	1102
					Business Bay, Aspect Tower Bldg D, 601	

Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61665.01	13	82	2	E124	Berna	04 4534749	
Called in	Time	Planned	Time	Delegated	Time	Stoppage	Service day
19/04/2011	8.49	19/04/2011	0.00	0.00	0.00	No	0

Called in work

AN IMAGE QUALITY

Description

black marks at the bottom

JO65690-need fixing film

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM4-9382-000000	FIXING FILM ASSEMBLY			DHLJF	1.00	318.40	318.40	925.00	0.00
							318.40		0.00
				0.00	0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr
ABE00201	IR7086	IR7086	501	PF	Repton School FZ-LLC	1303
					Nad Al Sheba 3&4	



Service order list

Page 12

PO Box 299 DUBAI									
Service order id	Status	Job type		Prio	Tech	Called in by	Phone	Cell Phone	
61670.01	13	82		2	E124	Anas	050 3089355		
Called in	Time	Planned	Time	Booked	Time	Delegated	Time	Stoppage	Service day
19/04/2011	9.55	20/04/2011	0.00		0.00		0.00	No	0
Called in work									
BC PAPER FEED									
Description									
jo 065694									
Actions									
Action description									
Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FF5-7829-030000	NR#ROLLER, PICK-UP			DHLJF	4.00	7.88	31.52	50.00	0.00
FF5-7830-030000	ROLLER, PICK-UP			DHLJF	4.00	7.85	31.40	50.00	0.00
FB6-0615-000000	ROLLER, FEED			DHLJF	6.00	7.29	43.74	75.00	0.00
							106.66		0.00
			0.00		0.00		0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr	
SXK00748	IR7105	IR7105	501	PF	Repton School FZ-LLC Nad Al Sheba 3&4	1303	
					299331 DUBAI		
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61671.01	13	82	2	E124	Anas	050 3089355	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
19/04/2011	9.55	20/04/2011	0.00		0.00	No	0
Called in work							
BC PAPER FEED							
Description							
jo 065693							
Actions							
Action description							
Start date	Time	End date	Time	Technician	Job type		
Item id	Description			Tech	Quantity	Cost price	Total
FF5-7829-030000	NR#ROLLER, PICK-UP			DHLJF	4.00	7.88	31.52
FF5-7830-030000	ROLLER, PICK-UP			DHLJF	4.00	7.85	31.40
FB6-0615-000000	ROLLER, FEED			DHLJF	6.00	7.29	43.74
						106.66	0.00
						0.00	0.00

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr			
TPY00209	IRC4580i	IRC4580i	200	CG	Emaar Mall	1102			
					Mall Management Office, Retail Dept.				
DUBAI									
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone		
61684.01	13	82	2	E124	Grape	04 3627508			
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day		
19/04/2011	11.03	20/04/2011	0.00		0.00	No	0		
Called in work									
AN IMAGE QUALITY									
Description									
black lines									
jo65691, need drum									
Actions									
Action description									
Start date	Time	End date	Time	Technician	Job type	Cost price	Total		
Item id	Description			Tech	Quantity		Price	Total	
0258B002AA	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	600.35	600.35	1,800.00	0.00
0257B002AA	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	947.47	947.47	2,300.00	0.00
						1,547.82		0.00	
			0.00	0.00		0.00	0.00		

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr			
------------	----------	-------	---------	-----------	----------	-------	--	--	--



Service order list

Page 13

MWM83175 IR2018 IR2018 101 CX Consulate General of Reput 1001
Bur Dubai, Visa Section

Service order id 61697.01 Status 13 Job type 82 Prio 2 Tech E128 PO Box # DUBAI
Called in 19/04/2011 Time 12.37 Planned 20/04/2011 Time Booked 0.00 Time Delegated 0.00 Time 0.00
Phone 050 1577898 Cell Phone
Stoppage No Service day 0

Called in work
AN IMAGE QUALITY

Description
drum problem(til 1:30pm)
JO67057-need drum & rollers

Action description	Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description				Tech	Quantity				
2101B002AA	00DRUM IR2018/2022/25/30				DHLJF	1.00	541.89	541.89	1,200.00	0.00
FF6-1621-000000	ROLLER, SEPARATION				DHLJF	2.00	22.22	44.44	100.00	0.00
								586.33		0.00
								0.00	0.00	

Machine id CZT04613 Model id IRC3580i Model IRC3580i Segment 200 Prod.area CG Customer Arabian Construction Co LL(Distr A205
Head office,Procurement, 6th Floor,603
Micco Bldg, Najda
2113 ABU DHABI

Service order id 61699.01 Status 13 Job type 82 Prio 2 Tech E122
Called in 19/04/2011 Time 13.14 Planned Time Booked 0.00 Time Delegated 0.00 Time 21/04/2011 0.00
Phone 055 9854344 Cell Phone
Stoppage No Service day 0

Called in work
BC PAPER FEED

Description
jo62332, need fixing film

Action description	Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description				Tech	Quantity				
FM3-1994-000000	FIXING FILM UNIT				ADSH	1.00	638.68	638.68	1,900.00	0.00
								638.68		0.00
								0.00	0.00	

Machine id CZT03610 Model id IRC3580i Model IRC3580i Segment 200 Prod.area CG Customer Zoo & Aquarium Public Instit Distr X001
Adminstration bldg

Service order id 61708.01 Status 13 Job type 82 Prio 2 Tech E111 1204 AL AIN
Called in 19/04/2011 Time 12.25 Planned Time Booked 0.00 Time Delegated 0.00 Time 19/04/2011 0.00
Phone 050 6731432 Cell Phone
Stoppage No Service day 0

Called in work
BQ PREVENTIVE MAINTENANCE

Description
JO 065934

Action description	Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description				Tech	Quantity				
0456B002BA	00DU IRC3380/2880				ADSH	1.00	555.61	555.61	2,000.00	0.00
0457B002BA	00DU IRC3380/2880				ADSH	1.00	1,039.22	1,039.22	2,900.00	0.00
0458B002BA	00DU (M) IRC2880/3380				ADSH	1.00	1,039.30	1,039.30	2,900.00	0.00
0459B002BA	00DU IRC3380/2880				ADSH	1.00	1,035.84	1,035.84	2,900.00	0.00
								3,669.97		0.00
								0.00	0.00	



Canon Emirates LLC 21/04/2011 11:37:37.757 AM ALICIAANOT

0.00 0.00 0.00 0.00

Machine id TPY00323 Model id IRC4580 Model IRC4580 Segment 200 Prod.area CG Customer Estee Lauder Middle East F; Dubai Airport Freezone E3 501 Distr 706

Service order id 61764.01 Status 13 Job type 82 Prio 2 Tech E123 Called in by Leyson PO Box 543UBAI Phone 04 2995600 Cell Phone 0
 Called in Time 19/04/2011 16.00 Planned 20/04/2011 Time Booked 0.00 Time Delegated 0.00 Time 0.00 Stoppage No Service day 0

Called in work AN IMAGE QUALITY

Description jo 065497

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM3-3779-000000	FIXING ASSEMBLY		230V	DHLJF	1.00	4,572.45	4,572.45	12,000.00	0.00
0257B002AA	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	947.47	947.47	2,300.00	0.00
0256B002AB	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	945.90	945.90	2,300.00	0.00
0255B002AA	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	946.28	946.28	2,300.00	0.00
FB6-3405-000000	ROLLER, PAPER PICK-UP			DHLJF	2.00	8.51	17.02	50.00	0.00
FC6-7083-000000	ROLLER, FEED/SEPARATION			DHLJF	2.00	8.19	16.38	100.00	0.00
FC6-6661-000000	ROLLER, SEPARATION			DHLJF	2.00	14.35	28.70	100.00	0.00
							7,474.20		0.00
						0.00	0.00	0.00	

Machine id MUR05382 Model id IR3035 Model IR3035 Segment 102 Prod.area CX Customer Extra Co. F. Fibre Glass & P Industrial Area No. 2 Distr 101

Service order id 61765.01 Status 13 Job type 82 Prio 2 Tech E102 Called in by Subair 6174 SHARJAH Phone 06 5432538 Cell Phone 0
 Called in Time 19/04/2011 16.15 Planned 20/04/2011 Time Booked 0.00 Time Delegated 0.00 Time 0.00 Stoppage No Service day 0

Called in work BC PAPER FEED

Description jo 065822

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
FM2-2955-000000	SEPARATION ROLLER ASSEMBLY			DHLJF	1.00	83.28	83.28	250.00	0.00
FL2-0964-000000	HOLDER, SEPARATION PAD, 2			DHLJF	1.00	14.99	14.99	100.00	0.00
FB6-3405-000000	ROLLER, PAPER PICK-UP			DHLJF	2.00	8.51	17.02	50.00	0.00
FC6-7083-000000	ROLLER, FEED/SEPARATION			DHLJF	2.00	8.19	16.38	100.00	0.00
FC6-6661-000000	ROLLER, SEPARATION			DHLJF	2.00	14.35	28.70	100.00	0.00
							160.37		0.00
						0.00	0.00	0.00	

Machine id DCF40892 Model id IRC2380i Model IRC2380i Segment 200 Prod.area CG Customer Zoo & Aquarium Public Instit Civic Center opp Jimi Mall Distr X001

Service order id 61818.01 Status 13 Job type 82 Prio 2 Tech E111 Called in by Ms. Arsha PO Box 120L AIN Phone 050 8383815 Cell Phone 0
 Called in Time 20/04/2011 13.49 Planned Time Booked 0.00 Time Delegated 0.00 Time 21/04/2011 0.00 Stoppage No Service day 0

Called in work AN IMAGE QUALITY



Service order list

Page 16

Description

black lines

jo65942, need drums

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
0456B002BA	00DU IRC3380/2880		C-EXV2	ADSH	1.00	555.91	555.91	2,000.00	0.00
0457B002BA	00DU IRC3380/2880		C-EXV2	ADSH	1.00	1,039.22	1,039.22	2,900.00	0.00
0458B002BA	00DU (M) IRC2880/3380		C-EX\	ADSH	1.00	1,039.30	1,039.30	2,900.00	0.00
0459B002BA	00DU IRC3380/2880		C-EXV2	ADSH	1.00	1,035.84	1,035.84	2,900.00	0.00
							3,670.27		0.00
						0.00	0.00	0.00	

Machine id	Model id	Model	Segment	Prod.area	Customer	Distr	
TNU00595	IRC4580	IRC4580	200	CG	Emaar Properties	1102	
					Dubai Mall Mgt Office Mezzanine floor		
					retail dept		
					9440 DUBAI		
Service order id	Status	Job type	Prio	Tech	Called in by	Phone	Cell Phone
61830	13	82	2	E124	Franklin	04 3627559	
Called in	Time	Planned	Time	Booked	Time	Stoppage	Service day
20/04/2011	15.01	21/04/2011	10.00		0.00	No	0

Called in work

BH RETURN TO FIT

Description

Actions

Action description

Start date	Time	End date	Time	Technician	Job type	Cost price	Total	Price	Total
Item id	Description			Tech	Quantity				
0256B002AB	00DU IRC4580/4080 CLC5151/4040			DHLJF	1.00	945.90	945.90	2,300.00	0.00
							945.90		0.00
						0.00	0.00	0.00	

Work time	Work costs	Travel time	Traveling costs	Trav. dist.	Parts
3.58	201.99	1.18	66.04	40.00	44,550.97

No. of service orders	Total costs	Total revenues
44	44,819.00	26,840.00