## WANJOHI ELVIS MUTHUMBI. SCT212-0043/2021

**COMPUTER ARCHITECTURE. LAB 3.** 

10 FH	LAB 3	
9/10/20	ET & Hazards . Here A here 9	
000	9. Read After Write.	
10		
Cycle	Reason : DADD needs	
CE!	value loaded into RI	A STATE
	by LD but LA might have	
1	not written it back.	
P	markly parmy and	
W	b. Write After Write	
4		
6	Reason: Both Muit and	
0	DADD write to RI. If	
2	DADD writer before MULT	
9	completes the contents	A STATE OF
ے ا	of Must will be lost	
1-	asiat planata (61) asiat	
	c. structural Hazard	
	Presidentes moves "Harren"	ACAMO SAN
	Reason: If procession has	
8	one multiply unit, then	
	second MULT must walt	
	for first to finish	
	· Ou	
	d Read After Write	
	a Read ATTEL OUT TE	
	maret was is housed and the	
	Reason: SD need value	
0	computed by DAAD in RT	
	but DADD may not have	
	written it back	The same of
-	The second second second second	

NT > Not taken

e. Read After Write (address dependancy)

Do wer for ar bare address which is written by babb how not written for yet, up may have wrong address

arially sollies of the -d

becaute to Ft If

E2: Branch Prediction

The counter how 4 state strongly not taken (00), weakly not taken (01), weakly taken (10), strongly taken

Predictor maker "taken"

prediction if counter it
in 10 or 11 states. When

branch is taken counter

increments (unless it is at
11).

When branch is not taken, counter decrements (unlass It is 00)

State	Name	Pred	ONTEK	Not To
00	SHT	HT	01	00
01.	THW	.NT.	. 10.	,00
10	WT	T	0 -	10
1)	TZ	7	11	10

Part B.

30	TO TO	E				
5	an the	3 8	D EX	1	0 -	MERATION X(i)
5 4 0 4	O	+0	0	+0	0 1	×(i)×
1	ZT	+	NT	+	ZT	Outcome
00	01	00 -	01	00	00	Counter
TT	Z	47	NT	NT T	エー	Prodiction
10	00	01	00	01	000	AFTE P
Z	4	Z	4	z	4	AFTER CORPECT?