TABELLA DEI COMANDI

μ	AıR	ZıR	A _{PC}	K _{PC}	AAC	AMAR	Ambr	S	L	Е	AA	A _B	AL	AL ₁	AL ₂	A_{T1}	K° _{T1}	K' _{T1}	A_{T2}	\mathbf{K}°_{T2}	\mathbf{K}_{T2}						Bus Indirizzi		Bu	s Dati
Ľ	٧	Z	⋖	K	<	₹	Αw		1		٧	۷	A	A	A	٧	×	¥	٧	¥	.X	Kb	Kac	Kmar			X ₁ X ₀	y ₁ y ₀	$\mathbf{x}_2 \ \mathbf{x}_1 \ \mathbf{x}_0$	y ₃ y ₂ y ₁ y ₀
1	0	ı	0	-	0	1	0	0	0	-	0	1	-	-	-	1	1	1	0	-	ı	1	-	0			01	01		
2	0	ı	0	ı	0	1	1	0	0	-	0	0	-	-	ı	0	-	-	0	-	ı	ı	-	1			-			
3	0	-	0	-	0	0	0	0	0	-	1	0	-	-	-	0	-	-	0	-	1	-	-	-					001	0101
4	0	ı	0	•	1	0	0	0	0	-	0	1	1	0	0	1	1	0	0	-	ı	ı	1	-			1	-	100	0110
5	0	-	0	-	1	1	0	0	0	-	0	0	-	-	-	1	1	0	0	-	-	-	1	1						
6		1	0	-	1	0	0	0	0	-	0	0	0	0	0	0	-	-	0	-	-	-	-	-					100	0100