TABELLA DEI COMANDI

Г.,	AıR	Z _{IR}	A _{PC}	K _{PC}	AAC	MAR	MBR	S	L	E	A	A _B	AL ₀	AL ₁	AL ₂	A _{T1}	K°_{T1}	K ' _{T1}	A _{T2}	K° _{T2}	\mathbf{K}_{T2}						Bus Indirizz		Bu	s Dati
μ	⋖	Z	Ā	¥	'∀	₹	Ą		1		٧	٧	₹	A	A	٧	٧	,X	٧	¥	¥						X ₁ X ₀	y ₁ y ₀	$\mathbf{x_2} \ \mathbf{x_1} \ \mathbf{x_0}$	y ₃ y ₂ y ₁ y ₀
1	0	ı	0	-	0	1	0	0	0	-	1	0	-	-	-	0	-	-	0	-	-	1	0				01	01		
2	0	-	0	-	0	1	1	0	1	-	0	0	-	-	-	0	-	-	0	-	-	-	1							
3	0	ı	0	-	0	0	0	0	0	-	0	0	-	-	-	1	-	-	0	-	-	ı	ı					1	001	0111
4	0	-	0	-	0	0	0	0	0	_	ı	_	-	_	-	1	1	1	1	0	0	ı	ı						101	1000
5	0	ı	0	-	0	0	0	0	0	-	0	1	-	-	-	0	-	-	0	-	-	ı	1					-	001	110
6	0	1	0	-	0	0	0	0	0	-	1	0	1	0	0	1	1	0	1	1	0	0	1					1	100	0101
7	0	ı	0	ı	0	0	0	0	0	-	0	0	-	-	-	1	1	0	1	1	0	ı	ı					1		
8	0	-	0	-	0	0	0	0	0	-	1	0	1	1	1	0	-	-	1	1	0	0	-					1	100	0101
9	0	-	0	-	0	0	0	0	0	_	0	0	-	-	-	0	-	-	1	1	0	-	ı					1		
10	1	1	0	-	1	0	0	q	C	-	0	0	-	-	-	0	-	-	0	_	-	0	-						111	0100