Raspberry Piz Pico GPIO Pinout

GPIO	Input Signal
GPIO - 0	checker_state[0]
GPIO - 1	checker_state[1]
GPIO - 2	checker_state[2]
GPIO - 3	core_standbywfe[0]
GPIO - 4	core_standbywfe[1]
GPIO - 5	forced_standby_status[0]
GPIO - 6	forced_standby_status[1]
GPIO - 7	watchdog_timer_expiration
GPIO - 8	core_parity_error[0]
GPIO - 9	core_parity_error[1]
GPIO - 10	checkpoint_error_after_boot

