

- ZZ1 Install label in silkscreened box after final wash. Text shall be 8 pt font. Text shall be per the Label Table in the PDF schematic.
- ZZ2 These assemblies are ESD sensitive, ESD precautions shall be observed.
- ZZ3 \blacksquare These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable. ZZ4 \blacksquare These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.
- ZZ5 ■INDICATION FOR COMPONENTS D* ARE GIVEN AT THEIR CATHODE SIDE.

COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 002_AWR



PCB VIEWED FROM TOP SIDE	BOARD #: PROC177	REV: B	SUN REV	: Not in version control
Assembly Layer Top	TID #: N/A			
PLOT NAME = Top Assembly Drawing	GENERATED : 18-01-	-2024 20:51:07	,	TEXAS INSTRUMENTS



COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 002_AWR

PCB VIEWED FROM BOTTOM SIDE	BOARD #: PROC177	REV: B	SUN REV	: Not in version control	
Assembly Bottom Layer	TID #: N/A				
PLOT NAME = Bottom Assembly Drawing	GENERATED : 18-01-	2024 20:51:07	1	TEXAS INSTRUMENTS	