Accident / Incident Report

Policy #:	**Policy Period:**	**CJS Contact:** Jamie 781-424-3371

Time and Place of Incident

Time: AM	**Date:** 01/09/26
Exact Location: 150 Flanders Rd. Westborough, MA	
Weather / Road Conditions Sunny / 40 degrees	

If Incident Occurred on a Job Site

Job Site Name: 150 Flanders Rd.	**Address:** 150 Flanders Rd. Westborough, MA
Customer Name: Limbach	**Customer Contact:**

CJS Driver/Operator and Vehicle/Equipment

Name: Bernie Rhouda	**DOB:** 11/08/1954
Address: 9 Border Rd. Holbrook, MA	**Telephone #:** 617-594-4048
License #: S91042507	**State of Issue:** MA
CJS Vehicle #: 54	**Make / Model:** 2003 Kenworth W900
CJS VIN #: 1XKWD40X33J392929	**Plate #:** S48143
Damage to CJS Vehicle / Equipment: N/A	

Other Vehicle / Driver

Operator's Name: N/A	**DOB:** N/A	
Address: N/A	**Telephone #:** N/A	**Sex:** N/A
License #: N/A	**State of Issue:** N/A	**Exp. Date:** N/A
Make / Model: N/A	**Color:** N/A	
VIN #: N/A	**Plate #:** N/A	**State Reg:** N/A
Owner's Name (if different): N/A		
Address: N/A		
Owner's Home Tel #: N/A	**Business Tel #:** N/A	
Damage to other Vehicle / Equipment: N/A		
Prior Damage Evident: N/A		
Insurance Company: N/A		

Property / Equipment Damage

Property Owner:	Limbach	**Phone #:**	
Property Address:	150 Flanders Rd. Westborough, MA / Jobstie		
Description of Damage:	Visible damage to the exterior corners of unit, as well as the under side near fans.		
Insurance Company:			

Injuries

Name:	**Injury:**	**Treatment:**
N/A	N/A	N/A

Witnesses

Name:	**Address:**	**Telephone:**
Bernie Rhouda		617-594-4048
Chris Dimmagio		617-968-9674

Police Report

Police Dept:	N/A	**Officer:**	N/A	**Report #:**	N/A
Citation Issued To:	N/A	**#:**	N/A		

Description of Accident

Picked up delivery from shop that was loaded on step deck trailer SDA-48-02 which consisted of three units. Drove to site in Westboro, MA and backed load up to crane which was setup at first location. No units were required to be offloaded at first location, so crane would need to relocate to 2nd location. Driver pulled truck out of the way so crane could pull out. While the driver was waiting for crane to move, he unstrapped the load in the parking lot. Once unstrapped, driver followed crane to 2nd setup location. When driver arrived at 2nd crane location on other side of building, he could not back in due to angle, cars in the way, and lawn area, so the truck was nosed up to the crane. First, 4 scrap units were taken down and set on the ground next to two units existing on the ground from the day before. One of the big new units existing on the ground was then picked to the roof, but did not line up with existing mounting location, so they brought it back down. When they brought the big unit back down, they set it on the upper deck of the trailer with the existing three units still not touched on the lower deck of trailer. Without realizing the upper deck of the trailer still had a layer of frost on it, the rigging job continued. The crew then picked off the three units from the lower deck of the trailer and sent to the roof for mounting. Once the new units were removed from lower deck of trailer, the scrap units previously set on the ground were loaded on to the lower part of the trailer. Before the the crane was to be moved, the crew needed a unit off of another trailer that was on site. Driver began to back out of the area from in front of the crane to drop current trailer in parking lot to strap units down and bring other trailer to be offloaded by crane. Driver moved truck forward to straighten out and then put in reverse and the big unit on the upper deck slid off the trailer falling to the ground. Truck was only on a very slight incline.