LSG Matter Information Worksheet

Matter Details: MOON EXPRESS INC

Open Date: 2/4/2026	**LSG Matter ID:**	787200.12831-00	**Assigned To:** Beuret, Tanner
	Damage Type:	Transit	
Date of Loss: 11/17/2025	**Property Type:**	Manufacturing Equipment/Industrial Machinery	**Line of Business:** Inland Marine
	Property Desc:	lamination machine	
	Catastrophe:		
	Claim Number:	F2X8198	**Claim Status:** Open
	Insured:	MOON EXPRESS INC	
	Claimant:	Treco Tech & Supply Inc.	
	Loss Location:	15601 ARROW HIGHWAY IRWINDALE, CA	**Budget:** $1,050.00

Adjuster: Mr. Nicholas Beebe (Nick)

Company:	Travelers Insurance
Address:	P.O. Box 430 Buffalo, NY 14240
Email:	NBEEBE@travelers.com
Business:	(630) 961-8928

Investigation

Site Inspection	No
Scope of Damage	Yes
Reparability	Yes
Salvage Market	Yes
Cause of Failure	No
ACV	Maybe
RCV	Yes

Notes: Claim Professional | Inland Marine Claim

Contacts:

Insured

Company:	MOON EXPRESS INC
Contact:	DIANA DONICHENKO
Email:	DIANA@MXTRUCKING.COM
Business:	(980) 214-4915

Claimant

Company:	Treco Tech & Supply Inc.

Matter Details: MOON EXPRESS INC

Open Date: 2/4/2026	**LSG Matter ID:**	787200.12831-00	**Assigned To:** Beuret, Tanner
	Damage Type:	Transit	
Date of Loss: 11/17/2025	**Property Type:**	Manufacturing Equipment/Industrial Machinery	**Line of Business:** Inland Marine
	Property Desc:	lamination machine	
	Catastrophe:		
	Claim Number:	F2X8198	**Claim Status:** Open
	Insured:	MOON EXPRESS INC	
	Claimant:	Treco Tech & Supply Inc.	
	Loss Location:	15601 ARROW HIGHWAY IRWINDALE, CA	**Budget:** $1,050.00

Notes: Contact info was not provided. From a document, Admin found a phone number (336-886-2401) but please confirm with adjuster that it's OK to contact them prior to reaching out.

Vendor

Company:	Barberan, S.A.
Email:	barberan@barberan.com
Notes:	Company is located in Spain. To call, dial 011 then 34 93 635 08 10.

Claim Notes

BUDGET: 4-6 hours / $700-$1,050

Adjuster's notes: "Damages: damage to lamination machine due to load shift.

Please review costs to repair lamination machine and confirm cost, appropriate and necessary.

Do not need to address ACV unless the repair cost is high and you think ACV may be less. I don’t think that’s the case tho."

Docs and photos provided.

BUDGET: 4-6 hours / $700-$1,050