
## Chaining MaxSonar Sensors, (AN Output)

## **Daisy Chaining using a Commanded Loop**



Repeat to add as many sensors as desired

## **Daisy Chaining using a Commanded Loop**

To chain the sensors, and have them to operate in sequential daisy-chained fashion, you do so by linking the TX of unit 1 to RX of unit 2 and so on. The BW pin is tied high on all of the parts. Then just strobe the first sensor's RX pin and all of the sensors will read the range in sequence. The analog values can then be read. The example above would use one pin to command the chain, and three analog to digital inputs.



MB1000DOC016 Revision Date: 03/05/08