





























Some extra things to put on the board for testing only

Not connected to the rest of the system!

Chebyshev Lowpass Filter

Som 7th order

50 fth 0th order

50 fth 7th order

50 fth 7th order

50 fth 7th order