1. Solder the Coin-Cell holder The slot should face the top

Quick Start Guide

- 2. Solder the Effect LED, mind the polarity (marked "+")
- matches with your LED 3. (Optionally) solder the switch Cut the shown trace first.

then solder the switch!

and enjoy the blinking / fading LED effects

4. Insert the battery, (eventually switch on,)

flat edge -

Please read also the safety advices on the back

Welcome _/_(ツ)_/_ This is the Chaos-West Token of the SHA2017 camp

For more Information, visit https://git.io/cwtkn

Safety Advices

The polarity of the battery is important! "+" of the holder must contact "+" of battery Do not have the CR2032 coin cell inserted

when the Li-Ion Charging IC is populated and USB is used. Only use LIR2032 or other single Li-Ion cells (3.6 V) for charging

Flip this card for a quick start guide