

1. Solder the switch like shown in the picture 2. Solder the Coin-Cell holder The slot should face the top 3. Solder the Effect LED, mind the polarity (marked "+") matches with your LED flat edge -4. Insert the battery (+ facing upwards), switch on, and enjoy the blinking / fading LED effects

Quick Start Guide (Rev. B)

Quick Start Guide (Rev. B)

in the picture

1. Solder the switch like shown

2. Solder the Coin-Cell holder

Please read also the safety advices on the back

Quick Start Guide (Rev. B) 1. Solder the switch like shown in the picture 2. Solder the Coin-Cell holder The slot should face the top 3. Solder the Effect LED, mind the polarity (marked "+") matches with your LED 4. Insert the battery (+ facing upwards), switch on, and enjoy the blinking / fading LED effects

Please read also the safety advices on the back Please read also the safety advices on the back


The slot should face the top 3. Solder the Effect LED, mind the polarity (marked "+") matches with your LED flat edge 4. Insert the battery (+ facing upwards), switch on, and enjoy the blinking / fading LED effects

Quick Start Guide (Rev. B) 1. Solder the switch like shown in the picture

2. Solder the Coin-Cell holder

3. Solder the Effect LED, mind

The slot should face the top



the polarity (marked "+") matches with your LED flat edge 4. Insert the battery (+ facing upwards), switch on, and enjoy the blinking / fading LED effects

Please read also the safety advices on the back Please read also the safety advices on the back

Quick Start Guide (Rev. B)

Quick Start Guide (Rev. B)

2. Solder the Coin-Cell holder

3. Solder the Effect LED, mind

the polarity (marked "+")

4. Insert the battery (+ facing

upwards), switch on, and

matches with your LED

The slot should face the top

in the picture

1. Solder the switch like shown

in the picture 2. Solder the Coin-Cell holder

1. Solder the switch like shown


The slot should face the top 3. Solder the Effect LED, mind

the polarity (marked "+")

- matches with your LED 4. Insert the battery (+ facing upwards), switch on, and
 - enjoy the blinking / fading LED effects

flat edge →

- Quick Start Guide (Rev. B) 1. Solder the switch like shown
- in the picture 2. Solder the Coin-Cell holder The slot should face the top
- 3. Solder the Effect LED, mind
- 4. Insert the battery (+ facing upwards), switch on, and



Please read also the safety advices on the back | Please read also the safety advices on the back