Report for full system test - 02.06.2025

During today's lab session, we mainly focused on the *IR sensor*. The initial code we had did not work as intended, so we had to make a few changes to it. At the end, we were able to make the code work in the correct way. This code along with the updated new system code can be found in the repository.

We also added a new 3d printed part for the switch, as requested during the last session.