
ZZZ These assemblies are ESD sensitive, ESD precautions shall be observed.


ZZ3 ■ These assemblies must be clean and free from flux and all contaminants. Use of no clean flux is not acceptable.

ZZ4 ■ These assemblies must comply with workmanship standards IPC-A-610 Class 2, unless otherwise specified.



## COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM TOP SIDE	BOARD #: SV601343	REV: A	SUN REV:	Not In VersionControl
IGNORE ->				
PLOT NAME = Top Assembly Drawing	GENERATED : 1/31/2	017 3:01:52	PM	TEXAS INSTRUMENTS



## COMPONENTS MARKED 'DNP' SHOULD NOT BE POPULATED. ASSEMBLY VARIANT: 001

PCB VIEWED FROM BOTTOM SIDE	BOARD #: SV601343	REV: A	SVN REV: Not In VersionControl		
	IGNORE ->				
PLOT NAME = Bottom Assembly Drawing	GENERATED : 1/31/2	017 3:01:53	PM TEXAS INSTRUMENTS		