U-Charts

- ► A U chart plots the **number of defects** (also called nonconformities) per unit.
- ▶ It is possible for a unit to have one or more defects but still be acceptable in function and performance.
- ► For example, you can use a U chart to monitor the following: The number of tears and pulls per 50 running feet of carpet.

