```
% Problem 4 code and result
clear all
clc
Emu = 29*10^6; % lb/in^2
Esig = 2*10^6; % 1b/in^2
Pmu = 50000; % lb
Psig = 10000; % lb
Wmux = 1000/12; % lb/in
Wsigx = 100/12; % lb/in
% Convert to W pramaters to mu_y and sig_y
Wsigy = sqrt(log((Wsigx/Wmux)^2+1));
Wmuy = log(Wmux) - 0.5*Wsigy^2;
% Now make equivalent normal mu and sig
pdf1 = pdf('lognorm', Wmux+20, Wmuy, Wsigy);
cdf1 = icdf('norm', cdf('lognormal', Wmux, Wmuy, Wsigy), 0, 1);
% Now get equivalent normal paramaters
WsiqP = pdf('norm', cdf1, 0, 1)/pdf1;
WmuP = (Wmux+20) - cdf1*WsigP;
L = 360; % in
I = 1330; % in^4
X i = []; % array to store x values
U_i = []; % array to store u values
B_i = []; % array to store beta values
E_i = []; % array to store error values
A_i = []; % array to store alphaa values
% First need to define the limit state function. We do not want beam
% displacement to be greater than 2 inches. Therefore following limit
% state function shall be used.
g(P, E, W) = 2 - [(PL^3)/(48EI) + (5/385)*((W*L^4)/(E*I))] = 0
% ______
% If g(P, E, W)<0 then we have failure
% To determine failure probability 'Pf' need to get beta, which is
% beta = g_mu/g_sig
% For the HL method need to implement an iterative procedure, which will
% hopefully converge to the approximate value of beta.
% For initilal condition use the mean value poins to get betal. After that
% let the iterative process update the inputs until beta converges. Also in
% the iterative portion of the code we will need to use the 'u' paramaters
% Code below will define initial value of beta
```

1

```
% Define q mu
g_mu = 2-((Pmu*L^3)/(48*Emu*I) + (5/385)*(((Wmux)*L^4)/(Emu*I)));
% To calculate g_sig requires that the derivative of g(P, E, W) are taken
% with respect to all the random variable (P, E, W). Then need to take the
% magnutude of the derivatives in order to obtain g_sig.
% Get derivatives
syms P1 E1 W1
g = 2-((P1*L^3)/(48*E1*I) + (5/385)*((W1*L^4)/(E1*I)));
gP = diff(g, P1);
% display('deriv qP')
% eval(subs(gP, E1, Emu))
gE = diff(g, E1);
% display('deriv gE')
% eval(subs(gE, [P1, E1, W1], [Pmu, Emu, Wmu]))
qW = diff(q, W1);
% display('deriv qW')
% eval(subs(gW1, E1, Emu))
% Now get g sig
g_sig = sqrt((eval(subs(gP, E1, Emu))*Psig)^2 + ...
    (eval(subs(qE, [P1, E1, W1], [Pmu, Emu, Wmux]))*Esiq)^2 + ...
    (eval(subs(gW, E1, Emu))*WsigP)^2);
% Now get beta
beta = g_mu/g_sig;
% Now get alphas
% For P
aP = -(eval(subs(gP, E1, Emu))*Psig)/g_sig;
% For E
aE = -(eval(subs(gE, [P1, E1, W1], [Pmu, Emu, Wmux]))*Esig)/g_sig;
% For W
aW = -(eval(subs(gW, E1, Emu))*WsigP)/g_sig;
% Calculate x's using following equation
% x new = x mu + beta*x sig*alpha
X=[Pmu + beta*Psig*aP Emu + beta*Esig*aE WmuP + beta*WsigP*aW];
% Calculate u's next
U = [(X(1) - Pmu)/Psig (X(2) - Emu)/Esig (X(3) - WmuP)/WsigP];
% Store values into arrays
X i=[X i;X];
U_i=[U_i;U];
B_i=[B_i;beta];
E_i = [E_i; 1];
A_i = [A_i; aP, aE, aW];
i=0;
```

```
% Now define while loop
while E_i(end)>0.0001 && i<100</pre>
    i=i+1;
    % Now make equivalent normal mu and sig
    pdf1 = pdf('lognorm', X_i(end,3), Wmuy, Wsigy);
    cdf1 = icdf('norm', cdf('lognormal', X_i(end,3), Wmuy, Wsigy), 0, 1);
    % Now get equivalent normal paramaters
    WsigP = pdf('norm', cdf1, 0, 1)/pdf1;
    WmuP = X_i(end,3) - cdf1*WsigP;
    g = 2-((X_i(end,1)*L^3)/(48*X_i(end,2)*I) + ...
        (5/385)*((X i(end,3)*L^4)/(X i(end,2)*I)));
    dP = eval(subs(gP, E1, X_i(end, 2)));
    dE = eval(subs(gE, [P1, E1, W1], [X_i(end,1), ...])
        X_i(end, 2), X_i(end, 3));
    dW = eval(subs(gW, E1, X_i(end, 2)));
    g_sig = sqrt((dP*Psig)^2 + (dE*Esig)^2 + (dW*WsigP)^2);
    % get new beta
    beta = (g - dP*Psig*U_i(end,1) - dE*Esig*U_i(end,2) ...
        - dW*WsigP*U_i(end,3))/g_sig;
    % store beta to vector
    B i=[B i;beta];
    % Now get alphas
    % For P
    aP = -(dP*Psig)/g_sig;
    % For E
    aE = -(dE*Esig)/g_sig;
    % For W
    aW = -(dW*WsigP)/g_sig;
    % Store alphas
    A_i=[A_i;aP, aE, aW];
    % Get new x's
    X=[Pmu + beta*Psig*aP Emu + beta*Esig*aE WmuP + beta*WsigP*aW];
    % store new x's
    X i=[X i;X];
    % Calculate new u's
    U = [(X_i(end,1) - Pmu)/Psig (X_i(end,2) - Emu)/Esig ...
        (X_i(end,3) - WmuP)/WsigP];
    % store new u's
    U_i=[U_i;U];
    % calculate new error
    e=abs(B i(end) - B i(end-1))/abs(B i(end-1));
    % store error value into array
    E_i=[E_i;e];
```

```
end
% Get probability failure
Pf = 1 - cdf('norm', B_i(end), 0, 1)
% Limit state function value at last iteration
*----
% Next employ MCS to compare results
% Implement MCS sampling with million samples
N = 1000000;
Nvar = 3;
% Define random vector U(N, Nvar)
U=rand(N,Nvar);
% Generate samples
XP = Pmu + Psig*icdf('norm', U(:,1), 0, 1);
XE = Emu + Esig*icdf('norm', U(:,2), 0, 1);
XW = \exp(Wmuy + Wsigy*icdf('norm', U(:,3), 0, 1));
% Calculate surrogate response using generated samples XP, XE, XW
disp = 2-((XP*L^3)./(48*XE*I) + (5/385)*(((XW)*L^4)./(XE*I)));
% Calculate failure probability
Pf_MCS = sum(disp<0)/N
Pf =
   0.1760
g =
 -1.6239e-08
Pf\_MCS =
```

Published with MATLAB® R2014b

0.1771