

Moore State Table:

Present State	Next State		Output(Z):
	X = 0	X = 1	
S0	S4	S1	0
S1	S5	S2	0
S2	S6	S3	0
S3	S7	S0	0
S4	S0	S5	1
S5	S1	S6	0
S6	S2	S7	0
S7	S3	S4	0