

In the above power trace, there are 11 dips. This could be due to the initial AddRoundKey step, as calculating the expansion key is computationally expensive.