Spirit Level



Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 24 labs

Covers these lab items: Hand Leveller; Levelers; Levellers; Spirit level; Spirit Level Bottle; Spirit level/water level; Sprit level

What it is used for

A spirit level checks whether a surface or component is horizontal or vertical using a liquid-filled vial and bubble. Use the correct reference surface and read the bubble carefully.

How to use

1. Inspect the level body, vial, and measuring edges for damage.
2. Clean the reference surface and the level's contact edges.
3. Place the level flat on the surface or component being checked.
4. Wait for the bubble to settle inside the vial.
5. Compare the bubble position with the marked centre lines.
6. Adjust the workpiece or installation until the bubble indicates the required level.
7. Check again from another suitable position when necessary.
8. Wipe the level clean and store it safely.

⚠ Safety

- Do not use a level with a cracked vial or bent body.
- Keep the level secure when working at height or near edges.
- Do not use the tool as a hammer or pry bar.

Care & storage

- Wipe the level clean and dry after use.
- Store it in a protective location and avoid dropping or striking it.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.