Vernier Caliper



Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 23 labs

Covers these lab items: Calipers; Calipers and measuring tools; Digital Calliper; Vanier calliper; Vernier; Vernier caliper; Vernier Caliper- Digital; Vernier caliper (electronics); Vernier Caliper (manual/Digital); Vernier calliper

What it is used for

A vernier caliper measures external dimensions, internal dimensions, and depth with precision. Choose the correct measuring surfaces and read the scale or digital display carefully.

How to use

1. Inspect the jaws, depth rod, sliding mechanism, and scale or display for damage.
2. Clean the measuring faces and the workpiece before measurement.
3. Close the jaws gently and check the zero reading.
4. Select the appropriate external, internal, or depth measuring feature.
5. Position the caliper squarely on the workpiece without excessive force.
6. Lock the slider if provided and read the scale or digital display.
7. Record the measurement with units and required precision.
8. Clean the caliper and store it in its protective case.

⚠ Safety

- Do not force the jaws or use the caliper as a clamp.
- Keep fingers clear of sharp workpiece edges.
- Do not measure moving or dangerously hot components.
- Handle the depth rod and measuring edges carefully to avoid damage.

Care & storage

- Wipe the caliper clean and dry after use.
- Store it in its case and check zero and calibration at recommended intervals.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.