Feeler Gauge



Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 7 labs

Covers these lab items: Feeler gauges; Tappet gauge

What it is used for

Use a feeler gauge to measure small gaps or clearances between two surfaces or machine components.

How to use

1. Select the gauge leaf or blade range suitable for the required clearance.
2. Inspect the blades for bends, rust, dirt, or damage.
3. Ensure the machine is stopped and safely isolated where required.
4. Clean the surfaces being measured before inserting the blade.
5. Slide the selected blade gently into the gap without forcing it.
6. Choose the blade that fits with slight, even resistance and record the size.
7. Clean and fold the gauge leaves back into the holder after use.

⚠ Safety

- Never measure moving or energized machinery unless a specifically approved safe method permits it.
- Do not force the blade into a tight gap.
- Handle thin blades carefully to avoid cuts or bending.
- Follow isolation procedures before working near moving components.

Care & storage

- Wipe blades clean and dry after use.
- Apply suitable rust protection when needed and store the blades folded.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.