Lux Meter



Category: **Electrical & Electronic Test Instruments** Type: **Short SOP** Priority: **Medium**

5 labs

Covers these lab items: Light meter; Lux meter; Lux meter/Light meter

What it is used for

A lux meter measures illuminance, or the amount of light falling on a surface. Use it to check lighting levels in workplaces, classrooms, laboratories, and other areas.

How to use

1. Inspect the meter, sensor, display, and battery before use.
2. Switch on the meter and select the appropriate measurement range if required.
3. Place the light sensor at the point where illumination needs to be measured.
4. Keep your body and hands from casting shadows on the sensor.
5. Wait for the reading to stabilize and record the lux value.
6. Switch off the meter and store it safely after use.

⚠ Safety

- Keep the meter dry and protect the sensor from impact.
- Do not stare directly into intense light sources while taking measurements.
- Use the instrument within its specified measurement range.

Care & storage

- Clean the sensor gently and store the meter in its protective case.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.