Thread Pitch Gauge



Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 5 labs

Covers these lab items: Thread wear indicator; Threading Gauge (Engineerin g); Threading Gauge (Plumbing)

What it is used for

A thread pitch gauge identifies the pitch of a screw thread by matching its teeth to the thread profile. Use the correct gauge leaf for metric or imperial threads as required.

How to use

1. Inspect the gauge leaves for wear, damage, rust, or bent teeth.
2. Clean the external or internal thread surface enough to see its profile.
3. Select a gauge leaf that matches the expected thread type and pitch range.
4. Place the leaf against the thread and check that the teeth align closely.
5. Try adjacent leaves until the best fit is found without forcing the gauge.
6. Read the marked pitch and clean and fold the gauge after use.

⚠ Safety

- Do not force the gauge into a thread or use it as a cutting tool.
- Keep fingers away from sharp or damaged gauge edges.
- Do not rely on a worn gauge for critical measurements.

Care & storage

- Wipe the leaves clean, keep them dry, and store the gauge folded in its case.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.