Hectolitre Weight Apparatus



Category: **Laboratory Instruments & Glassware** Type: **Short SOP** Priority: **Medium**

3 labs

Covers these lab items: Hectolitre weight apparatus

What it is used for

To determine the bulk density or hectolitre weight of grain using a standardised filling and weighing procedure.

How to handle

- Inspect the measuring container, filling funnel, strike-off tool, balance, and accessories for cleanliness and damage.
- Place the apparatus on a stable, level surface and verify the balance is zeroed or calibrated as required.
- Fill the measuring container using the prescribed method without compressing the grain or causing unintended settling.
- Level the grain surface using the specified strike-off procedure, then weigh the filled container as instructed.
- Record the result and test conditions, empty the apparatus, and clean it before the next sample.

Storage

- Store clean and dry in a protected laboratory cabinet or designated location.
- Keep weighing and measuring components together and protect them from impact, corrosion, and contamination.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.