Infrared Thermometer



Category: **Electrical & Electronic Test Instruments** Type: **Short SOP** Priority: **Medium**

2 labs

Covers these lab items: Infrared Thermometer; IR Thermometer

What it is used for

To measure surface temperature without direct contact using infrared radiation.

How to handle

- Inspect the thermometer lens, display, trigger, and battery compartment for damage or dirt.
- Select the correct measurement mode and emissivity setting where applicable, following the instrument manual.
- Aim at the intended surface from the recommended distance and keep the lens clean and unobstructed.
- Press the trigger and record the reading with units; avoid measuring through glass or steam unless the instrument is designed for it.
- Do not use a surface-temperature reading as a substitute for a clinical body-temperature measurement unless the device is approved for that purpose.

Storage

- Switch off the thermometer and clean the lens gently with the recommended material.
- Store in its protective case in a dry place away from extreme temperatures, dust, and impact.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.