Radiation Meter



Category: **Electrical & Electronic Test Instruments** Type: **Short SOP** Priority: **Medium**

2 labs

Covers these lab items: Radiation measuring instrument

What it is used for

To measure or survey radiation levels using an instrument appropriate for the radiation type and intended application.

How to handle

- Inspect the meter, probe, display, battery, and cables for damage before use.
- Confirm that the instrument is suitable for the radiation type, measurement range, and intended survey; check calibration status.
- Follow the radiation-safety plan and wear required personal protective equipment; do not handle unknown radioactive sources without authorization.
- Switch on the meter, allow it to stabilize as specified, and measure from the recommended position and distance.
- Record readings with units, location, time, and instrument details; follow site procedures if readings exceed established limits or an alarm occurs.

Storage

- Switch off the meter, clean it according to the manual, and protect the probe and connectors.
- Store in its designated case in a secure, dry location; maintain calibration and service records.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.