Set Square



Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 2 labs

Covers these lab items: Triangles (30°-60° and 45°)

What it is used for

To draw and check angles, perpendicular lines, and parallel lines in technical drawing or layout work.

How to handle

- Inspect the set square edges and angle markings for chips, cracks, warping, or worn graduations.
- Choose the appropriate 30°–60° or 45° set square for the required angle.
- Place the set square flat against the drawing surface and align its reference edge accurately.
- Draw along the edge using a suitable pencil or drawing instrument without excessive pressure.
- Keep the tool away from cutting operations unless it is specifically designed for that use.

Storage

- Wipe clean and dry after use to keep edges and markings clear.
- Store flat in a drawing case or rack to prevent bending, scratches, and breakage.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.