EC Meter



Category: **Laboratory Instruments & Glassware** Type: **Short SOP** Priority: **Medium**

1 labs

Covers these lab items: EC meter

What it is used for

An electrical conductivity (EC) meter measures how well a liquid conducts electricity, helping estimate dissolved ionic content. Calibrate the meter and use a clean probe for reliable results.

How to use

1. Inspect the meter, probe, cable, and sensor for damage.
2. Switch on the meter and confirm the selected measurement units.
3. Calibrate the meter using the recommended standard solution and procedure.
4. Rinse the probe with clean distilled or deionized water as appropriate.
5. Immerse the probe in the sample to the specified depth without touching the container.
6. Wait for the reading to stabilize and record EC, temperature, units, and sample details.
7. Rinse the probe and store it according to the manufacturer's instructions.

⚠ Safety

- Follow laboratory precautions for unknown or contaminated samples.
- Keep electrical connectors dry and do not immerse the meter beyond its rated limit.
- Handle calibration solutions according to their labels and safety instructions.

Care & storage

- Clean the probe after use and replace or maintain it according to the manufacturer's guidance.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.