Weather Instrument

Category: **Measuring & Marking Tools** Type: **Short SOP** Priority: **Medium** 1 labs

Covers these lab items: Thermometers, barometers, and anemometers for recording weather conditions

What it is used for

Weather instruments such as thermometers, barometers, and anemometers measure temperature, atmospheric pressure, and wind speed. Position instruments correctly and record readings with the appropriate units and observation time.

How to use

1. Inspect each instrument, sensor, display, and mounting point for damage.
2. Identify the measurement range, units, and operating instructions for each instrument.
3. Place the thermometer in a suitable shaded, ventilated location as specified.
4. Position the barometer away from disturbances and follow its installation guidance.
5. Install the anemometer in an exposed location with unobstructed airflow.
6. Allow readings to stabilize and record values with date and time.
7. Compare readings with expected ranges and report faulty or inconsistent measurements.

⚠ Safety

- Secure instruments and mounts against wind or accidental falling.
- Do not climb unsafe structures to reach measurement locations.
- Keep instruments away from electrical hazards and severe weather exposure when unsafe.
- Follow manufacturer guidance when handling glass thermometers or sensitive sensors.

Care & storage

- Clean sensors gently and store portable instruments in a dry, protected place.

Disclaimer: This SOP is prepared from general information available on the internet. For detailed instructions, refer to the manufacturer's original manual / file.